

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
KANTISHNA ROADHOUSE
Denali National Park & Preserve
McKinley Station
Denali Borough
Alaska

HAER AK-41

Photograph HAER AK-41-1 was previously transmitted to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Todd A Croteau, photographer, 2014

- | | |
|----------|--|
| AK-41-2 | Front elevation looking easterly showing the entry door and windows. |
| AK-41-3 | Front elevation looking easterly showing the entry door and windows. |
| AK-41-4 | 3/4 view of the front and side elevations looking easterly from the northwest corner. |
| AK-41-5 | Detail of the front and northwest elevations at the corner of the building. |
| AK-41-6 | Detail of the log construction at the northwest corner. |
| AK-41-7 | North side elevation wall with upstairs window. The vertical timbers are added reinforcements and were not part of the original construction. |
| AK-41-8 | 3/4 view of the back and northwest side walls from the northeast corner. |
| AK-41-9 | South side elevation with upstairs window. The vertical timbers were added for reinforcement. |
| AK-41-10 | Detail of the front entry door with "ROADHOUSE" sign. The vertical timber was added for reinforcement. |
| AK-41-11 | Detail of the front window on the first floor with some tools against the building. |
| AK-41-12 | Interior of the first floor looking toward the back and south walls. The vertical posts and tension cables were added to reinforce the collapsing structure. |