

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

LANGDALE COTTON MILL  
5910 19th Avenue  
Valley  
Chambers County  
Alabama

HAER No. AL-167

Jet Lowe, HAER Photographer, August 1997

- AL-167-1      General view looking north of Langdale Cotton Mill with cannery and icehouse in foreground. The community cannery, ca. 1930, provided commercial canning equipment for employees to preserve home-grown vegetables.
- AL-167-2      View of east elevation of Langdale Cotton Mill.
- AL-167-3      View of east elevation of original section of Langdale Cotton Mill, looking southwest from walk to powerhouse across channel.
- AL-167-4      View looking northwest of east elevation of original section of Langdale Cotton Mill. Note fire damage suggesting that this section is partially rebuilt.
- AL-167-5      Detail of columns and roof beams inside third floor of original section of Langdale Cotton Mill.
- AL-167-6      Interior view looking southeast of columns and roof beams on third floor of original section of Langdale Cotton Mill.
- AL-167-7      Detail view of north staircase in original section of mill.
- AL-167-8      View looking northeast of structural system in original section of mill.
- AL-167-9      Interior view of second floor machine shop showing roof trusses and clerestory windows.