

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
CAL,
38-SANFRA
157-

Maritime Museum
Beach Street, W of Polk St.,
San Francisco
San Francisco County
California

HABS No. CA-2225

Jet Lowe, photographer September 1981

- CA-2225-1 GENERAL VIEW, FRONT AND SIDE
- CA-2225-2 FRONT ELEVATION
- CA-2225-3 ENTRANCE
- CA-2225-4 GENERAL VIEW, REAR AND SIDE
- CA-2225-5 INTERIOR, ROTUNDA
- CA-2225-6 INTERIOR, GALLERY
- CA-2225-7 INTERIOR, STAIRWAY AND MURALS

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS CA-2225

AQUATIC PARK BATHHOUSE

(Maritime Museum)

San Francisco Maritime National Historical Park

Beach Street, West of Polk Street

San Francisco

San Francisco County

California

Photos were taken of the third floor of the Maritime Museum prior to restoration work being done on the murals. Photos were taken without a filter and views 43, 47, 48, 49, 50, 53, 54, 55, 56, 58 and 59 were taken at night using artificial lighting and should be adjusted with a blue filter for more accurate representation of the colors.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Todd A Croteau, photographer, 2012

- | | |
|------------|--|
| CA-2225-8 | View of the entire room from east end to west end showing terrazzo floor, all four columns and south wall. |
| CA-2225-9 | View of the entire room west end to east end showing terrazzo floor (buoy design), north and south walls columns to the left and stairway to the right. Also note the ship's wheel motif chandelier. |
| CA-2225-10 | View of entire room from east to west showing the north and east side of the columns and the compass rose motif on the terrazzo floor. |
| CA-2225-11 | Similar view in vertical orientation showing compass rose detail. |
| CA-2225-12 | Detail of ship's wheel motif in the central portion of the terrazzo floor. Also note the stairway up to the fourth floor. |
| CA-2225-13 | View of entire room from west to east showing the north and west side of the columns |
| CA-2225-14 | Detail of interior wall at east end of the room. The utility room/galley is behind the door. |

AQUATIC PARK BATHHOUSE
HABS CA-2225
INDEX TO PHOTOGRAPHS

- CA-2225-15 Detail of interior wall at west end of the room. A storage room is behind the door.
- CA-2225-16 Detail of the south wall at the east end showing bas relief sculpture and painted surfaces as well as terrazzo floor designs.
- CA-2225-17 Detail of the south wall at the center showing bas relief sculpture and stairways to fourth floor.
- CA-2225-18 Detail of the south wall at the west end showing bas relief sculpture and terrazzo floor designs along with stairway to the fourth floor at left.
- CA-2225-19 Detail of west end wall with bas relief and painted surface.
- CA-2225-20 Detail of column 1 - west elevation.
- CA-2225-21 Detail of column 1 - south elevation.
- CA-2225-22 Detail of column 1 - east elevatoin.
- CA-2225-23 Detail of column 1 - north elevation.
- CA-2225-24 Detail of column 2 - west elevation.
- CA-2225-25 Detail of column 2 - south elevation.
- CA-2225-26 Detail of column 2 - north elevation.
- CA-2225-27 Detail of column 3 - west elevation.
- CA-2225-28 Detail of column 3 - south elevation. Note that much of this has been replastered.
- CA-2225-29 Detail of column 3 - east elevation. Note the plaster repair in white.
- CA-2225-30 Detail of column 4 - west elevation.
- CA-2225-31 Detail of column 4 - south elevation.
- CA-2225-32 Detail of column 4 - east elevation.
- CA-2225-33 Detail of column 4 - north elevation.
- CA-2225-34 Detail of center door on the north side looking out towards the bay.
- CA-2225-35 Detail of ship's wheel motif for the brass door handle.

AQUATIC PARK BATHHOUSE
HABS CA-2225
INDEX TO PHOTOGRAPHS

- CA-2225-36 Detail of ship's wheel motif chandelier hanging in the room.
CA-2225-37 Detail of wall sconce in the room.


INDEX TO COLOR TRANSPARENCIES

Todd A Croteau, photographer, 2012

- CA-2225-38 (CT) View of room from east end looking west.
CA-2225-39 (CT) View of room from east end looking west along the north (waterview) wall.
CA-2225-40 (CT) View of room from east end looking west along the north wall (vertical orientation)
CA-2225-41 (CT) Detail of ship's wheel motif in the floor at the center of the room.
CA-2225-42 (CT) View of room from west end looking east. Note the buoy motif in the floor at right.
CA-2225-43 (CT) Detail of the buoy motif in the floor at the west end of the room.
CA-2225-44 (CT) View of room from west end looking east along the north wall.
CA-2225-45 (CT) Detail of the pantry room wall and door at the east end of the main room.
CA-2225-46 (CT) Detail of the swinging doors on the east end wall.
CA-2225-47 (CT) Detail of the doorway at the east end wall.
CA-2225-48 (CT) Detail of Column 1, west face.
CA-2225-49 (CT) Detail of Column 1, south face.
CA-2225-50 (CT) Detail of Column 1, east face.
CA-2225-51 (CT) Detail of Column 1, north face.
CA-2225-52 (CT) Detail of Column 2, north face.
CA-2225-53 (CT) Detail of Column 3, west face.
CA-2225-54 (CT) Detail of Column 3, east face.
CA-2225-55 (CT) Detail of Column 4, south face.
CA-2225-56 (CT) Detail of Column 4, east face.

AQUATIC PARK BATHHOUSE
HABS CA-2225
INDEX TO PHOTOGRAPHS

CA-2225-57 (CT)	Detail of Column 4, north face.
CA-2225-58 (CT)	Detail of west end wall.
CA-2225-59 (CT)	Detail of interior wall at west end looking east.



MARITIME MUSEUM - LAYOUT OF THIRD FLOOR

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
AQUATIC PARK BATHHOUSE
(Maritime Museum)
San Francisco Maritime National Historical Park
900 Beach Street
San Francisco
San Francisco County
California

HABS CA-2225

Photographs HABS CA-2225-1 through CA-2225-59 were previously transmitted to the Library of Congress. The following nine photographs were taken on January 31, 2013, following restoration of the ceiling art but before the room's side walls were painted. Thus the wall sconces and window banks are still covered in protective plastic, and conservation equipment appears throughout the images.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David G. De Vries, photographer, January 2013

- | | |
|------------|--|
| CA-2225-60 | Overview across the room to the northeast, showing the entry doors and the fifth window bank. |
| CA-2225-61 | Overview toward the southeast rear wall, from the east entry doors to the first bank of windows on the south. |
| CA-2225-62 | Overview to the west, showing the first, second, and third window banks, from the southeast to west. |
| CA-2225-63 | Overview toward the northwest front wall, showing the second window bank at the left, and the smaller fifth window bank at the right. The entry doors are just out of view to the right. |
| CA-2225-64 | An identical view to the northwest, with flash to emphasize the tonalities painted on the upper wall. The view also includes a surveyor's rod for scale, placed vertically at the center column. The scale is 13'-2" tall, and rests on the floor. |
| CA-2225-65 | Extreme wide angle view from the floor, showing the concentric color patterns on the ceiling at the center of the room, before re-installation of the chandelier. |
| CA-2225-66 | Detail, northeast wall between the fifth bank of windows on the east, and the entry doors. |
| CA-2225-67 | Detail of the east wall, adjacent to the entry doors. View to the east. |
| CA-2225-68 | Detail, southeast wall at the first window bank on the southeast perimeter. |