

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
CAL
48-MARI
IBN-

Mare Island Naval Shipyard,
Rubber Shop (Building 50)

HABS No. CA-1543-BN

California Avenue, west side across from Dry Dock 1 near 9th Street
Vallejo
Solano County
California

William B. Dewey, Photographer

April 1998

- CA-1543-BN-1 CONTEXTUAL VIEW SHOWING BUILDING 50 EAST ELEVATION,
WITH BUILDING 46 ON RIGHT; CAMERA FACING SOUTHWEST.
- CA-1543-BN-2 CONTEXTUAL VIEW BUILDING 50 ON RIGHT WITH BUILDING 52 ON
LEFT; CAMERA FACING NORTHWEST.
- CA-1543-BN-3 VIEW OF EAST ELEVATION ALONG CALIFORNIA AVENUE; CAMERA
FACING WEST.
- CA-1543-BN-4 VIEW OF WEST ELEVATION; CAMERA FACING NORTHEAST.
- CA-1543-BN-5 DETAIL OF WINDOWS IN ARCHED OPENING ON LEFT OF EAST
ELEVATION; CAMERA FACING WEST.
- CA-1543-BN-6 DETAIL OF SECOND FLOOR WINDOW WITH SPLAYED BRICK
HEADER, EAST ELEVATION; CAMERA FACING WEST.
- CA-1543-BN-7 DETAIL OF SECOND STORY WINDOWS AT ROOFLINE OF EAST
ELEVATION, NEXT TO BUILDING 52; CAMERA FACING
SOUTHWEST.
- CA-1543-BN-8 DETAIL OF SECOND STORY WINDOWS AND FRIEZE ON EAST
ELEVATION; CAMERA FACING WEST.
- CA-1543-BN-9 DETAIL OF MAIN DOORS ON EAST ELEVATION; CAMERA FACING
WEST.
- CA-1543-BN-10 DETAIL OF DOUBLE DOORS AND WINDOWS ON RIGHT SIDE OF
EAST ELEVATION; CAMERA FACING WEST.

MARE ISLAND NAVAL SHIPYARD,
Rubber Shop (Building 50)
HABS No. CA-1543- BN
INDEX TO PHOTOGRAPHS (Page 2)

- CA-1543-BN-11 DETAIL OF INTERFACE BETWEEN BUILDINGS 50 AND 46; CAMERA FACING WEST.
- CA-1543-BN-12 INTERIOR VIEW OF FIRST FLOOR SPACE SHOWING STAIRS ON NORTH WALL; CAMERA FACING NORTH.
- CA-1543-BN-13 INTERIOR VIEW OF FIRST FLOOR OFFICE ALONG EAST WALL, NEXT TO MAIN DOORS; CAMERA FACING NORTHEAST.
- CA-1543-BN-14 INTERIOR VIEW OF FIRST FLOOR SPACE ALONG SOUTH WALL, SHOWING STRUCTURAL SUPPORTS; CAMERA FACING SOUTHWEST.
- CA-1543-BN-15 INTERIOR VIEW OF SECOND FLOOR SPACE SHOWING BUILDING 46 WALL WITH BRICKED-IN ARCH AND LIFT IN FOREGROUND; CAMERA FACING NORTH.
- CA-1543-BN-16 INTERIOR VIEW OF SECOND FLOOR SPACE; CAMERA FACING SOUTH.
- CA-1543-BN-17 INTERIOR VIEW OF SECOND FLOOR SPACE SHOWING ROOF TRUSSES; CAMERA FACING NORTHEAST.