

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

STEAMBOAT SLOUGH BRIDGE

HAER CA-2291

(Bridge No. 24-52)

Spanning Steamboat Slough at California State Highway 160

Courtland vicinity

Sacramento County

California

INDEX TO BLACK AND WHITE PHOTOGRAPHS

- CA-2291-1 Photographic copy of aerial photograph. Original photograph located in California Department of Transportation (CALTRANS) Engineering Services Division, Structure Design Services & Earthquake Engineering, Office of Photogrammetry, Sacramento, California. Aerial view of bridge
- Don Tateishi and Ed Anderson, photographers, October 2002
- CA-2291-2 Distant view of east side of bridge, view looking west across the Sacramento River toward the slough from the County Road
- CA-2291-3 Distant view of east side of bridge, view of Shell boat gas pump and dock at the mouth of Steamboat Slough on west bank of Sacramento River, looking southwest from County Road
- CA-2291-4 General view of west side of bridge, view looking northeast from Grand Island Road
- CA-2291-5 General view of west side of bridge, view looking southwest from beach on north bank of Steamboat Slough
- CA-2291-6 General view of north side of bridge, view looking south from State Highway 160. Note gas station in the forefront at left in the photograph
- CA-2291-7 General view of north side, approach portal and concrete counterweight, looking south
- CA-2291-8 General view of south side, approach portal and concrete counterweight, looking north
- CA-2291-9 General view of east side looking west across the Sacramento River from County Road
- CA-2291-10 Detailed view of structural elements: steel framing and trusses, looking southeast from north bank of Steamboat Slough
- CA-2291-11 Detailed view of structural elements: steel framing and concrete earthquake retrofit on south abutment, looking northeast from Grand Island Road

STEAMBOAT SLOUGH BRIDGE

HAER CA-2291

Index to Photographs

(Page 2)

- CA-2291-12 Detailed view of structural elements: substructure, metal framing and underside of middle spans, looking south from north abutment
- CA-2291-13 Detailed view of structural elements: substructure, concrete pier and underside of north concrete span, looking south from north bank of Steamboat Slough under bridge
- CA-2291-14 Detailed view of structural elements: steel trusses, concrete pier and wood pylons on south side of bridge, looking north
- CA-2291-15 Detailed view of structural elements: south concrete counterweight, steel framing and trusses, looking northwest from State Highway 160
- CA-2291-16 Detailed view of structural elements: north concrete counterweight, steel framing and trusses, looking southeast from County Road

Don Tateishi, photographer, August 2004

- CA-2291-17 Detail view of structural elements: north concrete abutment, looking north from under bridge

Don Tateishi and Ed Anderson, photographers, October 2002

- CA-2291-18 Detailed view of structural elements: concrete deck, looking north
- CA-2291-19 Detailed view of structural elements: metal mesh deck, taken from top of south bascule, looking north
- CA-2291-20 Detailed view of decorative elements: timber wheel guard, metal lattice railing and steel truss, looking southeast from northwest approach portal
- CA-2291-21 Detailed view of traffic lights and gate located near the southeast concrete approach portal, looking northwest

Don Tateishi, photographer, August 2004

- CA-2291-22 Detailed view of fog bell on south side of bridge control operator's house, looking northeast
- CA-2291-23 Detailed view of plaque located on northwest approach portal, looking west. Plaque reads, "1924 DEDICATED BY THE BOARD OF SUPERVISORS, SACRAMENTO COUNTY CALIFORNIA"
- CA-2291-24 General view of bridge control operator's house, looking southwest from State Highway 160

Don Tateishi and Ed Anderson, photographers, October 2002

- CA-2291-25 General view of bridge control operator's house, looking north from top of south bascule
- CA-2291-26 General view of north facade of bridge control operator's house, walkway to main entry door, looking south
- CA-2291-27 General view of south facade of bridge control operator's house, view of windows, looking north

Don Tateishi, photographer, August 2004

- CA-2291-28 General view of east facade of bridge control operator's house, detailed view of door and window, looking west

Don Tateishi and Ed Anderson, photographers, October 2002

- CA-2291-29 General view of west facade of bridge control operator's house, detail view of windows, looking east
- CA-2291-30 Detailed view of underside of bridge control operator's house, looking north from north bank of Steamboat Slough
- CA-2291-31 General view of interior of bridge control operator's house, north half of interior, looking north from center of control house
- CA-2291-32 General view of interior of bridge control operator's house, south half of interior, looking south from center of control house
- CA-2291-33 Detailed view of engine generator inside bridge control operator's house, looking northeast
- CA-2291-34 Detailed view of air compressor inside bridge control operator's house, looking west
- CA-2291-35 Detailed view of electrical panel inside bridge control operator's house, looking southeast
- CA-2291-36 Detailed view of bridge control panel inside bridge control operator's house, looking south
- CA-2291-37 General view of bridge control operator's house and gear house, looking northeast from north bank of Steamboat Slough
- CA-2291-38 General view of south facade of gear house located above north bascule, looking north from bridge deck