

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

SPRING GAP-STANISLAUS HYDROELECTRIC SYSTEM,
SAND BAR DAM
(Sand Bar Diversion Dam)
Spanning the Middle Fork Stanislaus River
Cold Springs Vicinity
Tuolumne County
California

HAER CA-2306

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Marissa R. Rocke and David G. De Vries, photographers, July 2012

- CA-2306-1 A WIDE ANGLE VIEW TO THE NORTH OVER THE SITE OF THE FORMER DAM KEEPER'S VEGETABLE GARDEN, JUST EAST OF THE HOUSE SITE, TOWARD THE GATEHOUSE ATOP THE DIVERSION STRUCTURE.
- CA-2306-2 CONTEXT VIEW TO THE NORTHWEST, SHOWING THE GATEHOUSE, PARKING AREA, AND THE SITE OF THE PROPOSED NEW CONTROL BUILDING.
- CA-2306-3 LOOKING TOWARD THE EAST END OF THE INTAKE STRUCTURE, FROM THE SOUTH END OF THE FOOT BRIDGE OVER THE DIVERSION CHANNEL.
- CA-2306-4 OBLIQUE VIEW OF NORTH ELEVATION OF INTAKE STRUCTURE FROM THE TOP OF THE DAM. NOTE INTAKE ARCHES AT WATERLINE, AND GATEHOUSE NORTH ELEVATION.
- CA-2306-5 THE OLD WALL FORMING THE EAST END OF THE INTAKE STRUCTURE, ALSO SHOWING A SQUARE CONCRETE CABLE ANCHOR SET INTO THE GROUND.
- CA-2306-6 EAST END OF THE GATEHOUSE, ALSO SHOWING THE DIVERSION CHANNEL AND A MODERN CONTROL BUILDING IN LEFT DISTANCE. NOTE THE WEATHER SHIELD OVER THE GATE CABLES AND PULLEYS IN THE CENTER.
- CA-2306-7 GATEHOUSE OVERVIEW TO THE NORTHEAST FROM THE TOP OF THE DIVERSION STRUCTURE, SHOWING THE RESERVOIR AT LEFT.
- CA-2306-8 GABLE DETAIL, WEST END OF GATEHOUSE.

SPRING GAP-STANISLAUS HYDROELECTRIC SYSTEM,
SAND BAR DAM
HAER CA-2306
INDEX TO PHOTOGRAPHS
(Page 2)

- CA-2306-9 WEST GABLE DETAIL WITH SURVEYOR'S LEVEL ROD FOR SCALE.
THE ROD IS 13 FEET 2 INCHES LONG.
- CA-2306-10 GATEHOUSE INTERIOR, TO THE EAST, SHOWING THE GATE PULLEYS
AT RIGHT.
- CA-2306-11 GATEHOUSE INTERIOR, TO THE WEST, SHOWING AN UPRAISED
GATE OPERATING SCREW.
- CA-2306-12 DIVERSION CHANNEL WALL, TRASH RACK NEAR TUNNEL PORTAL,
STREAM GAUGE, AND WEIR AT EXTREME RIGHT.
- CA-2306-13 WEIR AND LOWER POOL, WITH STREAM GAUGE AT LEFT. LOWER
EDGE OF THE DAM IS VISIBLE AT LOWER EDGE OF IMAGE.
- CA-2306-14 LOWER POOL, LOWER NORTHWESTERN PART OF DAM, AND PART
OF THE NORTH ROCK RETAINING WALL AT RIGHT.
- CA-2306-15 VIEW ALONG DAM TOP TO THE NORTH WITH RESERVOIR TO THE
RIGHT AND LOWER POOL TO THE LEFT.
- CA-2306-16 VIEW FROM THE DAM TOP TOWARDS THE CONCRETE WALL
CONTAINING THE DIVERSION CHANNEL, THE MODERN CONTROL
BUILDING, AND THE STREAM GAUGE.
- CA-2306-17 VIEW FROM THE DAM TOP CENTER SHOWING THE LOWER POOL
AND THE WEIR.
- CA-2306-18 DETAIL, ROCK RETAINING WALL ON THE NORTH BANK.