

1-11-18
CO-43-A
1-11-18

**HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS**

High Line Canal,
Sand Creek Lateral

HAER No. CO-43-A

Beginning at the intersection of Peoria Street and the High Line Canal in Arapahoe County (City of Aurora), the Sand Creek Lateral extends fifteen miles in a northerly direction through Arapahoe County, the City and County of Denver, and Adams County to its end point, approximately one-quarter mile southeast of the intersection of D Street and 9th Avenue in Adams County (Rocky Mountain Arsenal, Commerce City Vicinity)

Commerce City vicinity
Adams County
Colorado

Note: The High Line Canal, Sand Creek Lateral, is located in Adams and Arapahoe counties and the City and County of Denver, Colorado. However, for shelving purposes at the Library of Congress, Adams County, Colorado, was selected as the "official location."

Documentation	30	exterior photographs
	30	data pages
	2	drawing sheets

Lisa Lynch, photographer; February 1998, photographs CO-43-A-1 through CO-43-A-3 and CO-43-A-14 through CO-43-A-30; and May 1998, photographs CO-43-A-4 through CO-43-A-13.

HAER No.	PHOTOGRAPH	CAMERA ORIENTATION
CO-43-A-1	HEAD GATE OF THE SAND CREEK LATERAL AT THE HIGH LINE CANAL ON THE SOUTH END OF THE PEORIA STREET BRIDGE	NORTH
CO-43-A-2	COURSE OF THE LATERAL THROUGH DEL MAR PARK	NORTHWEST

HAER No.	PHOTOGRAPH	CAMERA ORIENTATION
CO-43-A-3	1939 DROP STRUCTURE IN DEL MAR PARK SURMOUNTED BY RECENT PEDESTRIAN BRIDGE	SOUTHEAST
CO-43-A-4	SEGMENT OF LATERAL WEST OF C STREET (SECTION 10) ON THE ROCKY MOUNTAIN ARSENAL (RMA)	WEST
CO-43-A-5	HEAD GATE BETWEEN C AND D STREETS (SECTION 11)	NORTHWEST
CO-43-A-6	DROP STRUCTURE BETWEEN C AND D STREETS (SECTION 11)	SOUTHWEST
CO-43-A-7	SEGMENT OF LATERAL WITH YUCCA ALONG BANKS, SOUTH OF 6TH AVENUE (SECTION 10)	SOUTHWEST
CO-43-A-8	GENERAL VIEW OF LARGE DIVERSION STRUCTURE ON LATERAL WEST OF LOWER DERBY LAKE (SECTION 2)	NORTH
CO-43-A-9	DETAIL OF DIVERSION STRUCTURE WEST OF DERBY LAKE (SECTION 2) SHOWING DIVERSION GATE TO LAKE LADORA	SOUTHWEST
CO-43-A-10	CONCRETE DIVERSION CHANNEL EXTENDING TOWARD LAKE LADORA FROM THE DIVERSION STRUCTURE WEST OF LOWER DERBY LAKE (SECTION 2)	SOUTHWEST
CO-43-A-11	CONTINUATION OF LATERAL LEAVING THE DIVERSION STRUCTURE WEST OF LOWER DERBY LAKE (SECTION 2), SHOWING MEASURING GAUGE	WEST

HAER No.	PHOTOGRAPH	CAMERA ORIENTATION
CO-43-A-12	CONCRETE LINING ON A CURVING SEGMENT OF THE LATERAL NEAR THE NORTHEAST END OF LAKE LADORA (SECTION 2)	NORTHWEST
CO-43-A-13	TREES ALONG LATERAL SEGMENT AT THE NORTHERN END OF LAKE LADORA	EAST
CO-43-A-14	DAMAGED HEAD GATE NORTH OF LAKE LADORA (SECTION 2)	SOUTH
CO-43-A-15	CONCRETE CHECK DAM NORTHWEST OF LAKE LADORA (SECTION 2) WITH THE FORMER EGLI FARM IN THE DISTANCE	SOUTHEAST
CO-43-A-16	TWO HEAD GATES ABOUT 500 FEET NORTH OF 7TH AVENUE (SECTION 35)	NORTH
CO-43-A-17	DETAIL OF ONE OF THE HEAD GATES PICTURED IN CO-43-A-16 (SECTION 35)	SOUTH
CO-43-A-18	DETAIL OF HEAD GATE ABOUT 1,100 FEET NORTH OF 7TH AVENUE (SECTION 35), SHOWING CHANNEL IN WHICH GATE WAS RAISED AND LOWERED	WEST
CO-43-A-19	OUTLET OF PIPE WITH A CONCRETE CHANNEL SERVING THE HEAD GATE SHOWN IN CO-43-A-18	EAST
CO-43-A-20	HEAD GATE IN THE NORTHWEST QUARTER OF SECTION 35	NORTHWEST
CO-43-A-21	OUTLET PIPE AND CONCRETE CHANNEL FOR THE HEAD GATE PICTURED IN CO- 43-A-20	NORTHEAST

HAER No.	PHOTOGRAPH	CAMERA ORIENTATION
CO-43-A-22	HEAD GATE IN THE NORTHEAST QUARTER OF SECTION 35; NOTE CONTROL WHEEL	WEST
CO-43-A-23	OUTLET PIPE EMBEDDED IN CONCRETE FOR THE HEAD GATE SHOWN IN CO-43-A-22	EAST
CO-43-A-24	CULVERT WITH CONCRETE HEADWALL AND SIDEWALLS CARRYING THE LATERAL UNDER 8TH AVENUE	NORTHEAST
CO-43-A-25	DIVERSION STRUCTURE EAST OF FORMER BASIN F IN SECTION 26	SOUTH
CO-43-A-26	DIVERSION STRUCTURE WITH FORMER BASIN F IN DISTANCE (SECTION 26)	WEST
CO-43-A-27	DIVERSION STRUCTURE WITH CONCRETE SIDEWALLS AND CONCRETE CHANNEL BEYOND, A SHORT DISTANCE WEST OF D STREET ABOUT ONE-QUARTER MILE SOUTH OF 9TH AVENUE (SECTION 26)	NORTHWEST
CO-43-A-28	CONCRETE DIVERSION STRUCTURE ON THE WEST SIDE OF D STREET ABOUT ONE-QUARTER MILE SOUTH OF 9TH AVENUE (SECTION 26); THE LATERAL CONTINUES NORTHEAST WHILE A SIDE DITCH PROCEEDS NORTHWARD. THE DIVERSION STRUCTURE SHOWN IN CO-43-A-27 IS VISIBLE IN THE DISTANCE	NORTH

HAER No.	PHOTOGRAPH	CAMERA ORIENTATION
CO-43-A-29	VIEW OF THE DIVERSION STRUCTURE PICTURED IN CO-43-A-28 FROM THE CHANNEL OF THE LATERAL, SHOWING THE UPSTREAM FACE OF THE STRUCTURE	NORTH- NORTHEAST
CO-43-A-30	NORTHERN SEGMENT OF THE LATERAL IN THE NORTHWEST QUARTER OF SECTION 25 STRUCTURE PICTURED IN CO-43-A-28	EAST