

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, INSTRUMENT SHOP &
ELECTRICAL SHOP LEAN-TO
(U.S. Naval Base, Pearl Harbor, Naval Shipyard, Facility Nos. 3A &
3B)
Avenue E, between Sixth & Seventh Streets
Pearl Harbor
Honolulu County
Hawaii

HABS HI-445

HABS

HI-445

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, 2001

- | | |
|----------|--|
| HI-445-1 | Overall contextual view of Facility 3A/3B, oblique view from Facility 4 showing north and west sides. Facility 6 to far right. View facing south-southeast |
| HI-445-2 | Overall contextual view of Facility 3A/3B, oblique view of south and east sides from Building 7, Facility 4 roof visible over roof of Facility 3A. View facing northwest |
| HI-445-3 | Overall contextual view of Facility 3A/3B, east side view from roof of Facility 548. View facing west-northwest |
| HI-445-4 | Facility 3A, partial view of north side from Facility 4A, "STA-E22" on left. View facing south-southwest |
| HI-445-5 | Facility 3A/3B, oblique view of 3B with 3A behind from Facility 1456. view facing east |
| HI-445-6 | Facility 3A, interior overview of clerestory space, main entry reception beyond to the left. View facing northwest |
| HI-445-7 | Facility 3A, interior elevation overview from east end (high). View facing west-northwest |
| HI-445-8 | Facility 3A, interior of flat roof bay on south side clerestory to left, racks on wall to right. View facing east |

U.S. NAVAL BASE, PEARL HARBOR, INSTRUMENT SHOP &

HABS HI-445
INDEX TO PHOTOGRAPHS
PAGE 2

- HI-445-9 Facility 3A, interior detail of end wall, sliding door and clerestory at east end. View facing east-northeast
- HI-445-10 Facility 3A, interior of battery shop addition on north side of building showing overhead bridge crane, wall ladder to crane/platform. View facing west-northwest
- HI-445-11 Facility 3B, interior showing wood and block construction down length of space, steel table, empty shelves. View facing east
- HI-445-12 Facility 3B, interior detail of self-closing door into Facility 3A, wood support columns at east end of room, view facing north-northeast