

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
IND
82-EVA.V
1-

PERRY TOWNSHIP SCHOOL NO. 3 (Bockelman School)
Middle Mount Vernon Road and Eickhoff Road
Evansville Vicinity
Vanderburgh County
Indiana

Photographers: Camille Fife, Tom Salmon II, The Westerly Group

May, 1993

- IN-250-1 VIEW LOOKING NORTHWEST, FROM MIDDLE MOUNT VERNON ROAD, SHOWING THE SLIGHT RISE UPON WHICH THE BUILDING WAS CONSTRUCTED.
- IN-250-2 VIEW LOOKING NORTH, FRONT FACADE.
- IN-250-3 VIEW LOOKING NORTHEAST. MAJOR PORTIONS OF THE CEILING HAVE COLLAPSED (SEE PHOTO IN-250-11). THE BRACKETS WHICH WERE LET INTO THE BRICK TO SUPPORT THE SOFFIT OF THE ROOF OVERHANG ARE MISSING.
- IN-250-4 VIEW LOOKING NORTHEAST.
- IN-250-5 VIEW LOOKING SOUTHEAST.
- IN-250-6 VIEW TAKEN FROM THE NORTHWEST, LOOKING SOUTHEAST.
- IN-250-7 CLOSE UP VIEW OF THE MIDDLE MOUNT VERNON ROAD FACADE.
- IN-250-8 DETAIL OF THE FRONT DOOR AND THE LIMESTONE INSCRIPTION.
- IN-250-9 DETAIL OF A TYPICAL WINDOW AND A VENTILATOR JUST BELOW THE WINDOW SILL - THE ONLY INSTANCE OF SUCH PLACEMENT OF THIS FEATURE IN THE STRUCTURE.
- IN-250-10 DETAIL OF THE REAR DOOR AND ITS METAL-SHADED ELECTRIC LAMP.
- IN-250-11 DETAIL OF THE INTERIOR, LOOKING THROUGH AN INTERIOR DOORWAY TOWARD THE FRONT AND EAST WINDOW. NOTE: THIS PHOTOGRAPH SHOWS THAT THE BUILDING HAD BEEN CONVERTED TO A RESIDENCE FOLLOWING ITS USE AS A SCHOOL. IN ADDITION, THE HAZARDOUS CONDITION OF THE STRUCTURE'S INTERIOR IS EVIDENT. TWO CEILINGS WHICH ARE VISIBLE IN THE PHOTOGRAPH, (THE UPPER, PROBABLY ORIGINAL PLASTERED CEILING, AND A SECONDARY, ADAPTED CEILING) AS WELL AS CEILING JOISTS IN THE SOUTHERNMOST ROOMS HAVE COLLAPSED. BECAUSE OF THE DANGEROUS CONDITION OF THE INTERIOR OF THE BUILDING, ADDITIONAL INTERIOR PHOTOGRAPHY WAS NOT ATTEMPTED AT THIS TIME.