

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD.
3-DWMI.V
3-B

Blendon Estate, Barn
11747 Park Heights Avenue
Owings Mills Vicinity
Baltimore County
Maryland


HABS No. MD- 994-B

Photographer: (All views) Martin Stupich


November 1989

- MD-994 -B-1 SOUTH ELEVATION, VIEW TO NORTH
- MD-994 -B-2 DETAIL OF SOUTH ELEVATION, CENTER DOUBLE DOORS AND LOUVERED WALL VENTS
- MD-994 -B-3 OBLIQUE VIEW EAST SIDE FROM SOUTHEAST TO NORTHWEST
- MD-994 -B-4 OBLIQUE GENERAL VIEW FROM NORTHEAST CORNER, VIEW TO SOUTHWEST
- MD-994 -B-5 DETAIL, CUPOLA, VIEW TO SOUTHWEST
- MD-994 -B-6 NORTH ELEVATION, VIEW TO SOUTH
- MD-994 -B-7 OBLIQUE VIEW TO SOUTHEAST, SHOWING EARTHEN RAMP TO UPPER LEVEL
- MD-994 -B-8 OBLIQUE GENERAL VIEW OF SOUTHEAST CORNER, SHOWING OVERHANG AND LOWER LEVEL ACCESS
- MD-994 -B-9 SOUTH ELEVATION OF LOWER LEVEL
- MD-994 -B-10 LOWER LEVEL, WEST ROOM, SHOWING STONE WALL AND CEILING RAFTERS, VIEW TO NORTHWEST
- MD-994 -B-11 LOWER LEVEL EAST ROOM SHOWING STALLS, BEAMS, & RAFTERS
- MD-994 -B-12 LOWER LEVEL EAST ROOM, RAFTER SHOWING JOINT SPLICE DETAIL
- MD-994 -B-13 MAIN LEVEL, VIEW TO WEST/SOUTHWEST, SHOWING GENERAL STRUCTURAL CONFIGURATION
- MD-994 -B-14 VIEW OF MAIN LEVEL FROM EAST END
- MD-994 -B-15 MAIN LEVEL VIEW OF POST BEAM PEG DETAILS, VIEW OF SOUTHEAST CORNER FROM WEST
- MD-994 -B-16 INTERIOR ROOF STRUCTURE WITH CUPOLA STRUCTURE AT CENTER


EXTERIOR VIEW



INTERIOR VIEWS



Upper Level



Lower Level



NOT TO SCALE

KEY TO PHOTOGRAPHS BARN INTERIORS AND EXTERIORS

December 1989