

HABS
NY,
31-NEM9
108-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Music Hall (Carnegie Hall)
154 West Fifty-seventh Street
New York
New York County
New York

HABS No. NY-5717

Photographer: Stephen Senigo

November 1981

- NY-5717-1 HAND RAIL AT RECITAL HALL ENTRANCE
- NY-5717-2 ELEVATOR DOORS AT SECOND FLOOR
- NY-5717-3 HAND RAIL AT THIRD FLOOR ELEVATOR LOBBY
- NY-5717-4 HAND RAIL AT FOURTH FLOOR ELEVATOR LOBBY
- NY-5717-5 STAIR BETWEEN FIFTH AND SIXTH FLOORS
- NY-5717-6 DETAIL OF TYPICAL RISER
- NY-5717-7 DETAIL OF TYPICAL STAIR RAIL
- NY-5717-8 ELEVATOR SHIV ROOM

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
137
31-11810
158

ADDENDUM TO
MUSIC HALL (Carnegie Hall)
154 West Fifty-seventh Street
New York City
New York County
New York

HABS No. NY-5717
(Page 2)

Photographs HABS No. NY-5717-1 to HABS No. NY-5717-8 were previously transmitted to the Library of Congress on October 31, 1985.

Richard Pieper, Photographer, March, 1999.

(All index descriptions assume that front of building faces north.)

- NY-5717-9 VIEW OF ENTRY LOBBY FROM HALLWAY.
- NY-5717-10 VIEW OF ENTRY LOBBY FACING NORTHWEST.
- NY-5717-11 VIEW OF ENTRY LOBBY FACING SOUTHWEST.
- NY-5717-12 DOORWAY FROM ENTRY LOBBY TO RECITAL HALL LOBBY.
- NY-5717-13 DETAIL OF CEILING ARCH IN ENTRY LOBBY.
- NY-5717-14 DETAIL OF COLUMN CAPITAL AND BRACKETS IN ENTRY LOBBY.
- NY-5717-15 DETAIL OF PLASTER ORNAMENT FLANKING STAIRCASE IN ENTRY LOBBY.
- NY-5717-16 VIEW OF RECITAL HALL FACING NORTHEAST.
- NY-5717-17 VIEW OF RECITAL HALL FACING NORTHWEST.
- NY-5717-18 VIEW OF RECITAL HALL FACING SOUTHWEST.
- NY-5717-19 VIEW OF RECITAL HALL FACING SOUTHWEST.

- NY-5717-20 DETAIL OF PLASTER ORNAMENT ON BALCONY FACE.
- NY-5717-21 DETAIL OF PLASTER CARTOUCHE WITH CERUBS.
- NY-5717-22 DETAIL OF PLASTER ORNAMENT ON BRACKET SUPPORTING BALCONY.
- NY-5717-23 DETAIL OF PLASTER CAPITAL BENEATH BALCONY.
- NY-5717-24 DETAIL OF REMNANT ARCHWAY FLANKING BALCONY.
- NY-5717-25 VIEW OF LOGE ON WEST WALL.
- NY-5717-26 DETAIL OF COLUMN ON WEST WALL SHOWING CERAMIC TILE FIREPROOFING.
- NY-5717-27 VIEW OF RECITAL HALL LOBBY FACING EAST.
- NY-5717-28 DETAIL OF CAPITAL OF COLUMN IN RECITAL HALL LOBBY ABOVE HUNG CEILING.
- NY-5717-29 VIEW OF DOORWAY BACKSTAGE.
- NY-5717-30 VIEW OF HALLWAY EAST OF RECITAL HALL.
- NY-5717-31 VIEW OF SMALL ROOM SOUTH OF ENTRY LOBBY SHOWING GUASTAVINO TYPE VAULTING.
- NY-5717-32 DETAIL OF PLASTER ORNAMENT AND BOOK TILE CONSTRUCTION ABOVE HUNG CEILING IN SMALL ROOM SOUTH OF ENTRY LOBBY.
- NY-5717-33 DETAIL OF WOODEN WIRE MOLDING IN HALLWAY WEST OF ENTRY LOBBY.