

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
NY
57-61EFA
1-

GLENS FALLS DAM
100 to 450 feet west of the U. S. Route 9 bridge spanning the Hudson River
Glens Falls
Warren County
New York

HAER No. NY- 270

Photographer: Greg Troup

March and April 1993

- NY-270-1 WIDE-ANGLE VIEW OF THE GLENS FALLS DAM WITH THE NIAGARA MOHAWK POWER CORPORATION INTAKE STRUCTURE ON THE LEFT AND THE FINCH, PRUYN & COMPANY INTAKE STRUCTURE AND POWER CANAL ON THE RIGHT. FACING SOUTH TO SOUTHWEST.
- NY-270-2 VIEW OF THE SOUTHERN TWO-THIRDS OF THE DAM SHOWING THE GLENS FALLS BRIDGE OVER THE HUDSON RIVER ON THE LEFT, THE NIAGARA MOHAWK POWER CORPORATION PENSTOCKS AND INTAKE STRUCTURE AT THE SOUTHEAST CORNER OF THE DAM, AND THE DAM ITSELF. THE FINCH, PRUYN & COMPANY FOREBAY IS IN THE FOREGROUND. FACING SOUTH.
- NY-270-3 VIEW OF THE NORTHERN TWO-THIRDS OF THE DAM SHOWING THE FINCH, PRUYN & COMPANY INTAKE STRUCTURE AND FOREBAY CANAL ON THE RIGHT AND THE ICE-COVERED LOG CHUTE ALONG THE DAM. FACING SOUTH-SOUTHWEST.
- NY-270-4 GENERAL VIEW OF THE GLENS FALLS DAM FROM THE VICINITY OF THE LOG CHUTE. FACING EAST.
- NY-270-5 GENERAL VIEW OF THE GLENS FALLS DAM FROM THE VICINITY OF ITS SOUTHEAST END. THE LOG CHUTE IS IN THE BACKGROUND. FACING WEST-SOUTHWEST.
- NY-270-6 SOUTHWEST FACING VIEW OF THE ROMANESQUE ARCHES. HORIZONTAL LINE ABOVE THE ARCHES MARKS THE 1923 RAISING OF THE DAM. FLASHBOARDS CAP THE DAM.
- NY-270-7 SOUTHEAST FACING DETAIL VIEW OF ONE OF THE ROMANESQUE ARCHES ON THE DAM. HORIZONTAL LINE ABOVE THE ARCHES MARKS THE LINE OF THE 1923 RAISING OF THE DAM.
- NY-270-8 SOUTHEASTWARD FACING VIEW OF THE SOUTHEAST END OF THE DAM AT THE MEETING POINT WITH THE NIAGARA MOHAWK POWER CORPORATION INTAKE STRUCTURE ON THE LEFT.

- NY-270-9 DETAIL OF THE RACK AND PINION CONTROL GATE MECHANISM ON THE INTAKE STRUCTURE FOR THE NIAGARA MOHAWK POWER CORPORATION NO. 2 UNIT AT THE SOUTHEAST END OF THE DAM. FACING NORTHWEST.
- NY-270-10 THE LOG CHUTE IN THE GLENS FALLS DAM. FACING NORTHWEST.
- NY-270-11 A CLOSEUP VIEW OF THE LOG CHUTE SHOWING THE TURN BELOW THE GLENS FALLS DAM. FACING SOUTHWEST.
- NY-270-12 UPSTREAM VIEW SHOWING THE LOWER LOG POND LOG CHUTE IN THE MAIN CHANNEL OF THE HUDSON RIVER. THE LOG CHUTE IN THE DAM CAN BE SEEN IN THE BACKGROUND. FACING SOUTHWEST.
- NY-270-13 THE LOWER LOG POND AND LOG CHUTE. FACING WEST-SOUTHWEST.
- NY-270-14 COOPER'S CAVE AS VIEWED FROM THE BANK OF THE HUDSON RIVER BELOW THE FINCH, PRUYN & COMPANY POWERHOUSE. FACING SOUTH-SOUTHEAST.
- NY-270-15 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, October 3, 1923. Sheet 1-473, International Paper Company. Completing crest of dam. Section through the log chute (top); typical section through the dam (bottom).
- NY-270-16 Photographic copy of photograph (at the offices of Finch, Pruyn & Company, Glen Street, Glens Falls, New York), Beach?, Photographer, 1909.
PANORAMIC VIEW EAST TO SOUTHWEST OF THE GLENS FALLS DAM TAKEN FROM THE WEST END OF THE FINCH, PRUYN & COMPANY INTAKE STRUCTURE.
- NY-270-17 Photographic copy of photograph (at the offices of Finch, Pruyn & Company, Glen Street, Glens Falls, New York), Beach?, Photographer, March 28, 1913.
PANORAMIC VIEW OF THE HUDSON RIVER AT GLENS FALLS DURING THE MARCH 1913 FLOOD SHOWING OVERTOPPED GLENS FALLS DAM AND WASHED OUT BRIDGE. FACING SOUTHWEST.

- NY-270-18 Photographic copy of photograph (at the offices of Finch, Pruyn & Company, Glen Street, Glens Falls, New York), Beach?, Photographer, June 31, 1913.
PANORAMIC VIEW EAST TO SOUTHWEST OF THE GLENS FALLS DAM AFTER THE 1913 FLOOD TAKEN FROM THE WEST END OF THE FINCH, PRUYN & COMPANY INTAKE STRUCTURE.
- NY-270-19 Photographic copy of photograph (at the offices of Finch, Pruyn & Company, Glen Street, Glens Falls, New York), Beach?, Photographer, September 15, 1913.
PANORAMIC VIEW NORTHEAST TO SOUTHEAST OF THE GLENS FALLS DAM UNDER CONSTRUCTION.
- NY-270-20 Photographic copy of photograph (at the offices of Finch, Pruyn & Company, Glen Street, Glens Falls, New York), Beach?, Photographer, November 25, 1913.
VIEW SOUTHWEST TO NORTHWEST OF THE GLENS FALLS DAM BEFORE ACTIVATION. INTAKE STRUCTURES FOR INTERNATIONAL PAPER COMPANY AND FINCH, PRUYN & COMPANY ARE ON THE LEFT AND RIGHT, RESPECTIVELY.
- NY-270-21 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, September 23, 1913. Sheet 1-258, International Paper Company and Finch, Pruyn & Company. Concrete dam.
- NY-270-22 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, September 23, 1913. Sheet 1-258, International Paper Company and Finch, Pruyn & Company. Concrete dam. Detail showing cross sections through the dam.
- NY-270-23 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, July 3, 1913. Sheet 1-260, Finch, Pruyn & Company and International Paper Company. Detail of concrete dam and headgate wall.
- NY-270-24 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, July 3, 1913. Sheet 1-260, Finch, Pruyn & Company and International Paper Company. Detail of concrete dam and headgate wall. Detail showing plan view of place of joining of the dam and headgate wall.

- NY-270-25 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, July 3, 1913. Sheet 1-260, Finch, Pruyn & Company and International Paper Company. Detail of concrete dam and headgate wall. Detail showing profile of the north end of headgate wall.
- NY-270-26 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, July 3, 1913. Sheet 1-260, Finch, Pruyn & Company and International Paper Company. Detail of concrete dam and headgate wall. Detail showing the profile of the end of the headgate wall and south end of the Glens Falls Dam.
- NY-270-27 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, July 3, 1913. Sheet 1-260, Finch, Pruyn & Company and International Paper Company. Detail of concrete dam and headgate wall. Detail showing typical cross section through the dam.
- NY-270-28 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, October 3, 1923. Sheet 1-473, International Paper Company. Completing crest of dam.
- NY-270-29 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, October 3, 1923. Sheet 1-473, International Paper Company. Completing crest of dam. Section through the Finch, Pruyn & Company wing dam.
- NY-270-30 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, October 3, 1923. Sheet 1-473, International Paper Company. Completing crest of dam. Detail of block of concrete at meeting of flashboards at "G."
- NY-270-31 Photographic copy of ink on linen drawing (at the archives of Niagara Mohawk Power Corporation, 300 Erie Boulevard West, Syracuse, New York 13202), Strand, Draftsman, October 3, 1923. Sheet 1-473, International Paper Company. Completing crest of dam. Section through the Finch, Pruyn & Company headgates.

Glens Falls Dam
HAER No. NY-270
Key to Photographs
(Page 7)

