

Historic American Buildings Survey
Index To Photographs

HABS
OHIO,
18-CLEV,
43-

Brotherhood of Locomotive
Engineers Building
1365 Ontario Street
Cleveland
Cuyahoga County
Ohio

HABS No. OH-2357

Photographer: 01; 03-05; 07; 17-60; 68-74; 81, 83, 89, 90-99, 101-110: Jennie Jones
Photographer: 02; 06; 08-16; 61-17; 75-80; 82, 84-88, 100, 111-126: Rick Sherlock

April/May, 1989

Exterior

- OH-2357-01 View east: northwest/southwest facades 5/14/89
- OH-2357-02 View north: southwest facade/rear facade 5/08/89
- OH-2357-03 View west: southeast/northeast facades 4/07/89
- OH-2357-04 View southeast: Detail: auditorium entrance 5/04/89
- OH-2357-05 View east: Detail: Ontario entrance 5/04/89
- OH-2357-06 View northeast: Detail cornice on southwest facade 5/08/89
- OH-2357-07 View southeast: frieze/heads on northwest facade 5/04/89

Basement

- OH-2357-08 View east: 4/25/89
- OH-2357-09 View northeast: 4/25/89
- OH-2357-10 View west: 4/25/89
- OH-2357-11 View southwest: electrical room 4/25/89
- OH-2357-12 View west: electrical room 4/25/89

Roof/ elevator house

- OH-2357-13 View north: elevator house: exterior 4/25/89
- OH-2357-14 View northeast: interior elevator house 4/25/89
- OH-2357-15 View southwest: interior elevator house 4/25/89

Lobby area: Ontario entrance

OH-2357-16 View northeast: Detail: post box 4/25/89
OH-2357-17 View northeast: 4/12/89
OH-2357-18 View south: 4/12/89
OH-2357-19 View west: 4/12/89
OH-2357-20 View southeast: 4/12/89
OH-2357-21 View northwest: mural 4/12/89
OH-2357-22 View southeast: mural 4/12/89
OH-2357-23 View southwest: mural 4/12/89
OH-2357-24 View southwest: mural 4/12/89
OH-2357-25 View northwest: mural 4/12/89
OH-2357-26 View southwest: mural 4/12/89
OH-2357-27 View northwest: mural 4/12/89
OH-2357-28 View northeast: mural 4/12/89
OH-2357-29 View northeast: mural 4/12/89
OH-2357-30 View northeast: mural 4/12/89
OH-2357-31 View northeast: mural 4/12/89
OH-2357-32 View northeast: mural 4/12/89
OH-2357-33 View southeast: mural 4/12/89
OH-2357-34 View southwest: mural 4/12/89
OH-2357-35 View southwest: mural 4/12/89

Auditorium: lobby/foyer

OH-2357-36 View southwest 4/23/89
OH-2357-37 View northeast 4/23/89
OH-2357-38 View northeast: Detail: plaster work 4/23/89
OH-2357-39 View northeast: Detail: grate on Northeast
wall 4/23/89
OH-2357-40 View southwest: foyer 4/23/89
OH-2357-41 View northeast: foyer 4/23/89
OH-2357-42 View south: women's waiting room 4/23/89
OH-2357-43 View east: women's waiting room 4/23/89
OH-2357-44 View west: women's anteroom 4/23/89
OH-2357-45 View east: women's anteroom 4/23/89

Auditorium

OH-2357-46 View southeast: stage from under balcony 4/23/89

- OH-2357-47 View northwest: audience area from stage 4/23/89
OH-2357-48 View up: plaster work in ceiling 4/23/89
OH-2357-49 View up: Detail: ceiling plaster work 4/23/89
OH-2357-50 View up: Detail: ceiling plaster work 4/23/89
OH-2357-51 View east: stage wing 4/23/89
OH-2357-52 View east: Detail: plaster work on stage wing
4/23/89
OH-2357-53 View southeast: Detail: stage plaster work 4/23/89
OH-2357-54 View west: full column 4/23/89
OH-2357-55 View west: Detail: capital of column 4/23/89
OH-2357-56 View south: Detail: engaged column; frieze with
heads 4/23/89
OH-2357-57 View south: general view of auditorium from balcony 4/23/89
OH-2357-58 View east: general view of auditorium from balcony
4/23/89
OH-2357-59 View northeast: balcony 4/23/89
OH-2357-60 View south: exterior theatre wall and delivery
passage 4/23/89

First floor

- OH-2357-61 View southwest: hall 4/25/89

Second floor

- OH-2357-62 View southwest: hall 4/25/89

Third Floor

- OH-2357-63 View southwest: hall 4/22/89

Fourth floor

- OH-2357-64 View northwest: hall 4/20/89
OH-2357-65 View northwest: office area 4/20/89

Fifth floor

OH-2357-66 View southeast: hall /20/89
OH-2357-67 View southeast: hall 4/20/89

Sixth floor

OH-2357-68 View southeast: hall 4/07/89
OH-2357-69 View northeast: entrance to women's room
4/20/89
OH-2357-70 View northwest: hall 4/20/89
OH-2357-71 View southeast: hall 4/20/89
OH-2357-72 View northwest: office area 4/19/89
OH-2357-73 View southeast: office area 4/19/89
OH-2357-74 View south: office conference area 4/19/89
OH-2357-75 View east: office area 4/22/89

Seventh floor

OH-2357-76 View southeast: office area 4/22/89
OH-2357-77 View northeast: office area 4/22/89
OH-2357-78 View west: corner office area 4/22/89
OH-2357-79 View north: conference room 4/22/89

Eighth floor

OH-2357-80 View southeast: hall 4/18/89
OH-2357-81 View southwest: office area 4/18/89

Ninth floor

OH-2357-82 View southeast: hall 4/18/89
OH-2357-83 View southwest: hall 4/19/89

Tenth floor

OH-2357-84 View northwest: hall 4/17/89
OH-2357-85 View southwest: hall 4/17/89
OH-2357-86 View east: office area 4/17/89

OH-2357-87 View southeast: office area 4/17/89
OH-2357-88 View south: office area 4/17/89
OH-2357-89 View northwest: sign 4/19/89

Eleventh floor

OH-2357-90 View southeast: office area 4/14/89
OH-2357-91 View west: office area 4/14/89
OH-2357-92 View southwest: entrance to office 4/14/89
OH-2357-93 View east: stair well 4/13/89
OH-2357-94 View northwest: print shop 4/13/89
OH-2357-95 View south: print shop 4/13/89
OH-2357-96 View west: print shop 4/13/89

Twelfth floor

OH-2357-97 View west: office area 4/13/89
OH-2357-98 View southeast: brass window handle 4/13/89
OH-2357-99 View southeast: entrance to office 4/13/89
OH-2357-100 View northeast: entrance to washroom 4/19/89


Thirteenth floor

OH-2357-101 View southeast: passage 4/14/89
OH-2357-102 View southwest: passage 4/14/89
OH-2357-103 View south: office area 4/19/89
OH-2357-104 View southwest: passage/safes 4/19/89
OH-2357-105 View south: Detail: safe 4/14/89
OH-2357-106 View southeast: passage 4/19/89
OH-2357-107 View east: stairs 4/19/89
OH-2357-108 View northwest: outer passage 4/19/89
OH-2357-109 View northwest: office area 4/19/89
OH-2357-110 View northwest: passage 4/19/89


Photographic copies of architectural floor plans

- OH-2357-111 Plan of 4th to 12th Floors, Inclusive
- OH-2357-112 Typical Floor Framing Plan (3rd to 12th Floors Inclusive)
- OH-2357-113 Plan of Typical Panel
- OH-2357-114 General Arrangement Boiler Room Retaining Walls...
- OH-2357-115 Boiler Room Retaining Walls Details
- OH-2357-116 Boiler Room Retaining Wall Details
- OH-2357-117 Ontario Street Elevation
- OH-2357-118 St. Clair Avenue Elevation
- OH-2357-119 Boiler Room Retaining Walls Details
- OH-2357-120 South Elevation
- OH-2357-121 Section Thru Center Court Looking East
- OH-2357-122 Longitudinal Section Thru Auditorium
- OH-2357-123 General Details of First Story Spandrels of Ontario and St. Clair Ave.
Fronts
- OH-2357-124 Part Elevation of St. Clair Ave. Entrance
- OH-2357-125 General Details of Mezzanine Second and Third Story Spandrels of
Ontario and St. Clair Ave. Fronts
- OH-2357-126 Elevation of Main Cornice, Attic, 12th Story and Typical Story
Spandrels



EXTERIOR VIEWS





SOUTH ELEVATION



ST. CLAIR AVENUE ELEVATION





ONTARIO STREET ELEVATION




05 →


ONTARIO STREET LOBBY




AUDITORIUM




FIRST FLOOR




SECOND FLOOR




THIRD FLOOR




FOURTH FLOOR




FIFTH FLOOR




SIXTH FLOOR




SEVENTH FLOOR




EIGHTH FLOOR




NINTH FLOOR




TENTH FLOOR



ELEVENTH FLOOR



TWELFTH FLOOR



THIRTEENTH FLOOR

