

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

DEPARTMENT OF ENERGY, MOUND FACILITY, ELECTRONICS HABS OH-2470-D
LABORATORY BUILDING (E BUILDING)
One Mound Road
Miamisburg
Montgomery County
Ohio

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Camille Fife, photographer, August 1999

- OH-2470-D-1 View looking southeast from the roof of OSW Building, toward E Building (center ground of image). Part of H Building is in the immediate foreground. This photograph shows the relationship between E Building and others adjacent to it as well as some of the panorama of the site
- OH-2470-D-2 This image, looking due south shows the central part of the north wing of the building, a 2 story facade. In the foreground are several utility chases which span this elevation of the building
- OH-2470-D-3 Looking southwest, this photograph demonstrates the northeast corner of E Building, with a glimpse of part of the east entrance
- OH-2470-D-4 An image, looking southeast down the passage between E Building and M Building immediately to the east. The east entrance and the south wing of the building are visible
- OH-2470-D-5 A view looking northwest toward the southeast corner of the building. Just to the right of the corner is an indication of scale - an extended surveyor's rod
- OH-2470-D-6 This image, looking due north, demonstrates the south side of the building


DEPARTMENT OF ENERGY, MOUND FACILITY
HABS OH-2470-D

INDEX TO PHOTOGRAPHS


(Page 2)

- OH-2470-D-7 Looking southeast, this photograph shows the length of the north elevation of E Building
- OH-2470-D-8 A compilation of chase work characterizes this image, looking south, in the niche which slightly separates E Building from R Building, on the north side
- OH-2470-D-9 This photograph, taken from the main roof of E Building, looking north, shows two metal penthouses at right, a similar brick structure and some of the vents and other mechanical devices of the building
- OH-2470-D-10 A similar shot to the previous image, this photograph, looking northwest, provides a closer image of the brick penthouse and other devices
- OH-2470-D-11 Looking west, this interior photograph, taken in the second floor of E Building, demonstrates one of the typical corridors of the structure
- OH-2470-D-12 A corridor on the first floor of the building, looking west, shows some of the typical interior finishes in this section. At the end of the hallway, the corridor turns right after entering the next adjacent structure
- OH-2470-D-13 This image, looking south, shows a typical corridor in the laboratory area of the building, where numerous pipes were required to carry the various utilities needed for procedure and safety equipment
- OH-2470-D-14 This photograph, looking southwest in Room 107, demonstrates some of the laboratory equipment and facilities which have been recently used in E Building
- OH-2470-D-15 An image, looking east into Room 112A, filled with technical equipment pertinent to the building's recent use
- OH-2470-D-16 One wall of the original E Building is visible in the back of this image, looking west in Room 142, a typical laboratory space


Key to Photographs
U. S. Department of Energy
MOUNDS FACILITY
Electronics Laboratory Building
(E Building)
HABS No.OH-2470-D (Page 3)




Key to Photographs
 U. S. Department of Energy
 MOUNDS FACILITY
 Electronics Laboratory Building
 (E Building)
 HABS No.OH-2470-D (Page 4)



E BUILDING - FIRST FLOOR



Key to Photographs
U. S. Department of Energy
MOUNDS FACILITY
Electronics Laboratory Building
(E Building)
HABS No.OH-2470-D (Page 5)



E BUILDING · SECOND FLOOR

