

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ELLSWORTH AIR FORCE BASE,
MESS AND ADMINISTRATION BUILDING
(Building No. 1101)
2279 Risner Drive
Black Hawk Vicinity
Meade County
South Dakota

HABS No. SD-21-S

Bill Groethe, Photographer, October, 1997

Note: 4" x 5" images were made from 4" x 5" negatives.

- SD-21-S-1 NORTHWEST CORNER; VIEW TO SOUTHEAST.
- SD-21-S-2 WEST SIDE; VIEW TO EAST.
- SD-21-S-3 SOUTHWEST CORNER; VIEW TO NORTHEAST.
- SD-21-S-4 SOUTH BACK; VIEW TO NORTH.
- SD-21-S-5 EAST SIDE; VIEW TO WEST.
- SD-21-S-6 NORTHEAST CORNER; VIEW TO SOUTHWEST.
- SD-21-S-7 INTERIOR VIEW OF MAIN ENTRANCE LOOKING INTO RECEPTION
SPACE OF WELLNESS CENTER OFFICES; SHOWING DOORWAY TO
CORRIDOR ACCESSING REHABILITATION AND TESTING FACILITIES
AND SMALL ROOM BEHIND; NEAR CENTER OF WEST SIDE OF
OCCUPIED PORTION; VIEW TO SOUTH.
- SD-21-S-8 INTERIOR VIEW OF COMMUNITY WORK SPACE IN WELLNESS
CENTER OFFICES; SHOWING VIEW INTO RELAXATION ROOM,
MORE OFFICES, AND HALLWAY TO UNOCCUPIED PORTION OF
BUILDING; SOUTHWEST CORNER OF OCCUPIED PORTION;
VIEW TO SOUTHWEST.
- SD-21-S-9 INTERIOR VIEW OF MECHANICAL ROOM; SHOWING
EQUIPMENT; SOUTHEAST CORNER OF UNOCCUPIED
PORTION; VIEW TO EAST.

- SD-21-S-10 INTERIOR VIEW OF RECEPTION/WAITING AREA IN REHABILITATION AND TESTING FACILITIES; SHOWING EXTERIOR WINDOWS; NORTHEAST CORNER OF OCCUPIED PORTION; VIEW TO NORTHEAST.
- SD-21-S-11 INTERIOR VIEW OF RECEPTION/WAITING AREA IN REHABILITATION AND TESTING FACILITIES LOOKING INTO CORRIDOR ACCESSING TESTING ROOMS; NORTHEAST CORNER OF OCCUPIED PORTION; VIEW TO NORTHWEST.
- SD-21-S-12 INTERIOR VIEW OF WORKOUT ROOM IN REHABILITATION AND TESTING FACILITIES; SHOWING BREAK/DRESSING ROOMS BEYOND; NEAR SOUTHEAST CORNER OF OCCUPIED PORTION; VIEW TO SOUTHWEST.
- SD-21-S-13 INTERIOR VIEW OF BREAK/DRESSING ROOM IN REHABILITATION AND TESTING FACILITIES; SHOWING CASEWORK AND EXTERIOR WINDOW; SOUTHEAST CORNER OF OCCUPIED PORTION; VIEW TO WEST.
- SD-21-S-14 INTERIOR VIEW OF VESTIBULE SEPARATING REHABILITATION SPACE, TESTING ROOM, AND CORRIDOR TO WORKOUT ROOM LOOKING INTO CORRIDOR; NEAR CENTER OF OCCUPIED PORTION; VIEW TO SOUTHEAST.
- SD-21-S-15 INTERIOR VIEW OF UNOCCUPIED CONTROLLED COMPUTER ROOM LOOKING AT EXIT DOOR AND OFFICE; NORTHWEST CORNER OF UNOCCUPIED PORTION; VIEW TO SOUTH.
- SD-21-S-16 INTERIOR VIEW OF COMMUNITY SPACE LOOKING AT CLOSET AND OFFICES; CENTER OF UNOCCUPIED PORTION; VIEW TO SOUTH.
- SD-21-S-17 INTERIOR VIEW OF VESTIBULE SEPARATING LOCKER ROOMS, CHANGING ROOMS AND RESTROOM BEYOND; SOUTHWEST CORNER OF UNOCCUPIED PORTION; VIEW TO NORTHWEST.

- SD-21-S-18 INTERIOR VIEW OF ENCLOSED LOADING DOCK
LOOKING AT DOORWAY TO OFFICE SPACES AND OLD
FREEZER AREA; SHOWING DOORS TO EXTERIOR; SOUTH
SIDE OF UNOCCUPIED PORTION; VIEW TO SOUTHEAST.
- SD-21-S-19 INTERIOR VIEW OF OLD WALK-IN COOLER LOOKING INTO
WALK-IN FREEZER; NEAR SOUTHEAST CORNER OF
UNOCCUPIED PORTION; VIEW TO SOUTHEAST.
- SD-21-S-20 INTERIOR VIEW OF REHABILITATION AREA IN
REHABILITATION AND TESTING FACILITIES; NEAR CENTER OF
OCCUPIED PORTION; VIEW TO NORTHEAST.

KEY TO PHOTOGRAPHS

Ellsworth Air Force Base
Mess and Administration Building
(Building No. 1101)
HABS No. SD-21-S
(Page 4)

