

INDEX TO PHOTOGRAPHS

HABS
TEX
84-GALV,
44A-

Fort Point District Boat Yard, Pattern Warehouse
(Galveston District Annex Building No. 2)
2000 Fort Point Road
City of Galveston
Galveston County
Texas

HABS NO. TX-3401-A

Eugene R. Foster, Jr., Photographer, April 1994

- TX-3401-A-1 DISTANT VIEW OF NORTHEAST FRONT
- TX-3401-A-2 PERSPECTIVE VIEW TOWARD THE WEST
- TX-3401-A-3 VIEW OF NORTHEAST FRONT
- TX-3401-A-4 DETAIL VIEW OF NORTHEAST FRONT, EAST BAYS 18-22
- TX-3401-A-5 DETAIL VIEW OF NORTHEAST FRONT, CENTRAL BAYS 15-19
- TX-3401-A-6 DETAIL VIEW OF NORTHEAST FRONT, WEST BAYS 12-16
- TX-3401-A-7 VIEW OF NORTHWEST END, CORNER BAYS 1 AND 12
- TX-3401-A-8 PERSPECTIVE VIEW TOWARD THE EAST
- TX-3401-A-9 DETAIL VIEW OF SOUTHWEST REAR, BAYS 1-4
- TX-3401-A-10 DETAIL VIEW OF SOUTHWEST REAR, BAYS 5-7
- TX-3401-A-11 DETAIL VIEW OF SOUTHWEST REAR, BAYS 8-11
- TX-3401-A-12 VIEW OF SOUTHEAST END, CORNER BAYS 11 AND 22
- TX-3401-A-13 DETAIL OF TYPICAL FOUR-SASH WINDOW
- TX-3401-A-14 DETAIL OF TYPICAL THREE-SASH WINDOW
- TX-3401-A-15 DETAIL OF TYPICAL CASEMENT WINDOW

FORT POINT DISTRICT BOAT YARD, PATTERN WAREHOUSE
(GALVESTON DISTRICT ANNEX BUILDING NO. 2)
HABS NO. TX-3401-A
INDEX TO PHOTOGRAPHS
PAGE NO. 2

TX-3401-A-16 DETAIL OF STORM-PROOF ELECTRICAL FIXTURE

TX-3401-A-17 DETAIL OF TYPICAL SECOND FLOOR COLUMN

TX-3401-A-18 DETAIL OF PATTERN CRATES AND ORIGINAL INTERIOR LIGHT FIXTURE,
BAY 19, SECOND FLOOR

TX-3401-A-19 DETAIL OF SECOND FLOOR MONO-RAIL SUSPENSION BRACKETS, BAY 17,
SECOND FLOOR

TX-3401-A-20 DETAIL OF STORM WATER DRAINAGE SYSTEM, BAY 1 SECOND FLOOR

TX-3401-A-21 DETAIL OF INTERIOR HANDRAIL AND EXTERIOR COLUMN, BAY 1, SECOND
FLOOR

TX-3401-A-22 DETAIL OF ORIGINAL STAIR WITH 1986 LANDING, BAY 1, FIRST FLOOR