

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

SEATRAN OHIO

HAER TX-111

(Ohio)

(Mission San Jose)

Beaumont Reserve Fleet, Neches River

Beaumont vicinity

Jefferson County

Texas

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jet Lowe, photographer, April 2009

TX-111-1	Starboard profile view.
TX-111-2	3/4 view off the starboard bow.
TX-111-3	3/4 view off the port bow.
TX-111-4	3/4 view off the port quarter.
TX-111-5	Poop deck, view looking to port.
TX-111-6	View looking aft toward funnel from starboard bridge wing.
TX-111-7	Poop deck, view looking forward.
TX-111-8	View looking aft from the spar deck toward superstructure.
TX-111-9	View of spar deck looking forward from the port bridge wing.
TX-111-10	Upper deck, view looking forward across the gap in the spar deck.
TX-111-11	View from forward spar deck of aft cargo crane. Note six pairs of rails for securing loaded rolling stock on the upper deck below.
TX-111-12	View of upper deck looking aft with crane on upper deck above.
TX-111-13	View from aft spar deck of cargo cranes and upper deck below.
TX-111-14	Forward cargo crane looking aft toward port side.
TX-111-15	Detail view of cargo tackle at head of forward cargo crane.

SEATRRAIN OHIO
HAER TX-111
INDEX TO PHOTOGRAPHS
Page 2

TX-111-16	View looking aft along spar deck.
TX-111-17	Forecastle, looking aft.
TX-111-18	Forecastle, looking toward anchor windlass from starboard side.
TX-111-19	Boat deck, starboard side, view looking forward with life boat and davits in foreground.
TX-111-20	Wheelhouse, looking aft with chart room in background.
TX-111-21	Wheelhouse, looking forward.
TX-111-22	Gyro compass room on starboard side of upper bridge deck.
TX-111-23	Captain's office on starboard side of upper bridge deck.
TX-111-24	Captain's stateroom on port side of upper bridge deck.
TX-111-25	Captain's head on port side of upper bridge deck.
TX-111-26	Bathroom on port side of bridge deck connecting to hospital.
TX-111-27	View of galley, looking aft.
TX-111-28	Upper deck cargo space, looking forward.
TX-111-29	Bosun's and maintenance man's quarters, upper deck aft, port side.
TX-111-30	Detail view of space between hull and longitudinal bulkhead under the second deck, looking aft on starboard side.
TX-111-31	View of the hold, looking aft.
TX-111-32	View of the hold, looking forward.
TX-111-33	View of the second deck, looking forward from amidships.
TX-111-34	View of the second deck, looking aft from amidships.
TX-111-35	View of engine room looking aft from starboard side showing high and low pressure turbines.
TX-111-36	View of steering gear from port side.
TX-111-37	Steering room looking aft from starboard side showing hydraulic steering gear manufactured by the Stetson Ross Machine Co., Seattle.
TX-111-38	Detail view of instruction board for changing the steering gear.

INDEX TO COLOR TRANSPARENCIES

Jet Lowe, photographer, April 2009

TX-111-39 (CT)	3/4 view off the starboard quarter.
TX-111-40 (CT)	Bosun's and maintenance man's quarters, upper deck aft, port side.
TX-111-41 (CT)	Captain's stateroom on port side of upper bridge deck.
TX-111-42 (CT)	View looking aft along spar deck.
TX-111-43 (CT)	View looking aft from the spar deck toward superstructure.
TX-111-44 (CT)	Detail view of cargo tackle at head of forward cargo crane.
TX-111-45 (CT)	Forecastle, looking aft.