

THOMAS POWERS RANCH, LIVESTOCK BARN
4373 North Highway 224
Snyderville
Summit County
Utah

HABS No. UT-126-B

HABS
UTAH
22-SNYD,
2B-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
INTERMOUNTAIN SUPPORT OFFICE - DENVER
National Park Service
U.S. Department of the Interior
P.O. Box 25287
Denver, CO 80225-0287

HISTORIC AMERICAN BUILDINGS SURVEY
THOMAS POWERS RANCH, LIVESTOCK BARN
(HABS No. UT-126-B)

HABS
UTAH
22-SNYD,
2B-

Livestock Barn

This structure is a wood frame barn located just east of the large barn (structure UT-126-A).

This barn is rectangular in shape with the long axis oriented east to west. The barn has a gabled roof with the gables at the east and west ends. The east end of the roof extends outward over the east side providing cover over the hayloft entryway which is located near the top of the east wall.

The east facade contains three openings which are located along the center line of the wall. The lowest of these openings is a square wood frame door attached to an overhead rail which allows it to slide to the south in order to open. Above the sliding door is a large square opening; no door or covering is present. Above this opening is a larger rectangular opening leading to the hayloft. Like the opening below it, no door covering is present.

The west side of this livestock barn has six openings. Two are doorways and three are windows and one is a louvered vent. One doorway consists of a sliding door mounted on an overhead rail which allows it to slide northward to open. The louvered vent opening is located near the top of the west wall between two of the windows. Of these two windows, the southern one is covered with boards and the northern one has no covering or glass panes present. The third is a six pane window with panes presented and is located north of the sliding door.

On the north side of this barn is a series of wooden pens consisting of wooden rail fences and wood frame dividers. The west end of these pens are covered by a roof which extends outward from the north wall. The roof consists of a wood frame covered with corrugated metal sheeting.

The south wall of this barn is also the north wall of the milking barn (UT-126-D).