

"Green Hill" Brick Dependency
Virginia Road No. 728
Long Island Vicinity
Campbell County
Virginia

HABS No. VA-604

HABS
VA
16-LONI.V,
II-

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Eastern Office, Division of Design and Construction
143 South Third Street
Philadelphia 6, Pennsylvania

"GREEN HILL" BRICK DEPENDENCYHABS
VA
16-LONI.V
II-

Address: Virginia Road No. 728, Long Island Vicinity,
Campbell County, Virginia

Present Owner: L. H. Holland and brothers

Present Use: Hay Storage. Used by the owners

PART I. HISTORICAL INFORMATION

"Green Hill" plantation was built by Samuel Pannill who first bought 600 acres from William and Moses Fuqua in 1797, and added to and developed the plantation 'til his death in 1864.

PART II. ARCHITECTURAL INFORMATION

A. General Statement

1. Architectural character: This is one of three buildings in the "Upper Town" group that is constructed of brick. Its original use is not known. Very little alteration has been done to the original structure and the building retains most of its early architectural elements.
2. Condition of fabric: The majority of masonry work is in fair condition. Portions of the north wall have started to fall out but confined to one section only. The building is presently used for hay storage and very much abused.

B. Technical Description of Exterior

1. Overall dimensions: Approximately 22' x 34', one-and-a-half stories high.
2. Foundations: Field stone
3. Wall construction: Burned red brick laid over a stone foundation. Brick laid in a common bond with flat arches of brick over window heads. Windows and doors have stone sills.
4. Bulkheads: West basement entrance built of field stone and constructed independently of brick walls. About 5' x 8' in size Door to basement missing.
5. Chimneys: One square brick chimney (3 stretchers, 1 header by 2 stretchers, 1 header) built against east wall on exterior.

6. Openings:

- a. Doorways and doors: One exterior door opening mid-way in south wall, first floor. One exterior door opening into basement entrance on west side. Doors missing. There is a transom opening above the south door, but the sash is missing.
- b. Windows and shutters: Window frames constructed of wooden members set between brick openings. Sash missing. Two window openings located in south wall, for double hung window sash; two window openings opposite in north wall for double hung window sash. One window opening on second floor in west gable end for double hung window sash. All sash missing.

7. Roof:

- a. Shape, covering: Gable roof presently covered with sheet metal. Shed roof over basement entrance with metal covering.
- b. Eaves: Boxed eaves are formed by the projection of the ceiling joists past the brick walls about 10", and are covered with a beaded fascia board and soffit board. Gable ends are finished with a tapered and beaded verge board terminating at the eave.

C. Technical Description of Interior

1. Floor plans: One room each on first and second floors.
2. Stairway: Located against west end of building.
3. Flooring: Wooden floor both levels.
4. Wall and ceiling finish: Walls are exposed brick; ceiling exposed joists that are beaded with floor boards over.
5. Heating: Fireplace with mantelpiece, east end of first floor.

D. Site

1. General setting and orientation: Situated northeast of the main house with its long axis oriented east and west, and its entrance on the south side.
2. Enclosures: Modern fences attached. Modern shed attached to northeast end of building.