

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
VA
42-CLOV.V
15-

EDGEWOOD FARM, FRAME TENANT HOUSE
West side of State Route 600,
.8 mile north of State Route 778
Clover Vicinity
Halifax County
Virginia

HABS NO. VA-1290-J

Photographer: Anthony Masso

September 1990

- VA-1290-J-1 View to northwest.
- VA-1290-J-2 View to southeast.
- VA-1290-J-3 Interior view to southeast in southwest room on
first floor, showing mantelpiece framing stove
thimble, and treatment of walls, ceilings, and
woodwork. Door to enclosed stair at extreme right.