

HABS  
WASH  
17-SEAT,  
18-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS & IMAGES

U.S. IMMIGRANT STATION AND ASSAY OFFICE  
(~~Federal Building, Immigration and Naturalization Service~~)  
(INS BUILDING)  
815 Airport Way  
Seattle  
King County  
Washington

HABS No. WA-215

Mary Peck, Photographer      July 1996

- WA-215-1              Context View from Northwest corner of roof showing junction of Airport Way and Dearborn Streets. Camera pointed Northwest.
- WA-215-2              North Elevation.
- WA-215-3              South Elevation.
- WA-215-4              West Elevation.
- WA-215-5              East Elevation.
- WA-215-6              Detail showing main entry of facade on Airport Way, West door. Camera pointed South.
- WA-215-7              Detail showing main entry on Airport Way. Camera pointed South.
- WA-215-8              Facade detail West end of building. Camera pointed South.
- WA-215-9              View of East wall of recreation yard on North side of building showing second floor dormitory windows, third floor office windows and dentils at cornice. Camera pointed Southwest.
- WA-215-10              View of tile roof and dormer detail. Roof covers building attic. Camera pointed Northwest from Southeast corner of roof.
- WA-215-11              Terra cotta soffit and cornice over window to fourth floor women's restroom, South wall of building.
- WA-215-12              Detail of building facade on Airport Way showing lantern. Camera pointed South.
- WA-215-13              Detail of terra cotta soffit and cornice detail at Northwest side of building.
- WA-215-14              Entry vestibule, first floor. Camera pointed Northwest.

- WA-215-15            Entry vestibule, first floor. Camera pointed North.
- WA-215-16            Interior view of first floor stairwell at the West end of the building.  
Camera pointed North.
- WA-215-17            Interior view of second floor corridor, detention section, East end of the  
building. Camera pointed East.
- WA-215-18            Interior view of fourth floor corridor. Camera pointed Northwest from  
Northeast corner of the building.
- WA-215-19            Interior view of dormitory 2-A, second floor. Camera pointed  
Southwest.
- WA-215-20            Interior view of third floor office. Camera pointed West.
- WA-215-21            Interior view of Immigration Courtroom, Room #308, third floor at West  
end of the building. Camera pointed North.
- WA-215-22            Interior view of second floor elevator floor monitor and elevator  
interior. Camera pointed North.
- WA-215-23            Interior view of fourth floor women's restroom. Camera pointed West.
- WA-215-24            Interior of men's shower in the basement at the East end of the building.  
Camera pointed Northwest.
- WA-215-25            Interior view of attic at East end of the building showing Otis elevator  
pulley and cable housing. Camera pointed North.
- WA-215-26            Interior view of attic at East end of the building showing Otis elevator  
meters. Camera pointed North.
- WA-215-27            Kodak Century View #7 with 4 x 5 back used until late 1960s to take  
INS photographs.