

CAMP WILLIAMS
(127th Infantry Regiment Cantonment Area Subcomplex, Building No.
119)
(Camp Williams-Volk Field National Guard Training Center)
119 Peoria Street
Camp Douglas
Juneau County
Wisconsin

HABS WI-381-A-3
HABS WI-381-A-3

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MIDWEST REGIONAL OFFICE
National Park Service
U.S. Department of the Interior
601 Riverfront Drive
Omaha, NE 68102

HISTORIC AMERICAN BUILDINGS SURVEY

CAMP WILLIAMS

(127TH INFANTRY REGIMENT CANTONMENT AREA SUBCOMPLEX–BUILDING 119)

- Location: 119 Peoria Street
Camp Williams-Volk Field National Guard Training Center
Camp Douglas, Juneau County, Wisconsin
- Significance: Building 119 was constructed in 1940-1941 as a company mess hall for the 127th Infantry Regiment Cantonment Area.
- History: Building 119 was designed by Lieutenant Colonel Henry C. Hengles and constructed between 1940 and 1941 by the Works Progress Administration. It was a company mess hall for 127th Infantry Regiment Cantonment Area and replaced a wood-frame mess hall. The building currently functions as a private-room barracks.¹ A detailed history of the subcomplex is provided in the document for HABS No. WI-381-A.

Description:

- A. General Statement: This building is constructed on a slight west northwest-east southeast axis. Directions have been simplified to north-south-east-west within this section.
1. Architectural character: Building 119 is a one-story, astylistic utilitarian, front-gabled structure constructed of tan, glazed tile with red brick accents at the gables, corners and doorways. A wall chimney and heavy timber purlins and lintels adorn the building. The roof is sheathed with asphalt shingles.
 2. Condition of Fabric: The exterior fabric is good. Alterations are limited to the wholesale replacement of windows and doors, as well as the enclosing of sidewall eaves with aluminum and replacing the top portion of the chimney with red brick. The building has been converted into private-room barracks. Thus the interior is completely renovated.
- B. Exterior Description:
1. General Description: Oriented on an east-west axis, the gabled west (main)

¹“New Mess Halls at Camp Williams,” *WNGR* 17:3 (May 1940): 5; Photographs of the WMA at Camp Williams, circa 1958, Located in Camp Williams Files, Facilities Management Office, Department of Military Affairs, Madison, WI.

CAMP WILLIAMS

127TH INFANTRY REGIMENT CANTONMENT AREA SUBCOMPLEX-BUILDING 119

HABS No. WI-381-A-3

Page 2

facade is pierced by a central double door flanked by replacement double-hung sashes. A louvered vent underlined with a thin concrete sill is set in the gable peak. The open eaves are supported by five heavy timber purlins.

Beginning at the southwest corner, the south facade is pierced by six regularly placed windows (the fourth of which is infilled with matching tile), an open expanse and two smaller windows that coincide with the former kitchen area and an original doorway at the southeast corner.

The east gabled endwall is defined by a central wall chimney flanked by large window opening filled with replacement, one-over-one, double-hung sashes.

Starting at the northeast corner, the north facade is pierced by a pair of window openings – the second of which is converted into a doorway. An original doorway that once provided access to the dining hall has been infilled with matching tile. Six regularly placed window openings that mirror those on the south facade occupy the remainder of the facade.

2. Overall Dimensions: The building is 75' x 25'.
3. Foundations: The foundation is of poured concrete.
4. Walls: The walls are constructed with 12" x 5" tan glazed tile and are 8" thick. The tile is accented by red brick at the corners, around original doorways, within the wall chimney and on the gables at the eaves.
5. Roof: The gabled roof is sheathed with asphalt shingles placed on 6" wide boards. The sidewall eaves are enclosed with aluminum and the eaves on the gables are open. Five exposed timber purlins adorn the west gable, while six support that facing east. They measure 6" x 6" and project 15½". Both gables are underscored by red brick accents.
6. Openings:
 - A. Windows: Windows are regularly placed throughout the building. Each has a concrete sill and a 5½" thick timber lintel. Generally, the windows are fitted with replacement, metal, one-over-one, double-hung sashes.

The two windows on the west (main) facade are 37" x 60". The two smaller double-hung sashes on the south facade that coincide with the former kitchen

CAMP WILLIAMS

127TH INFANTRY REGIMENT CANTONMENT AREA SUBCOMPLEX-BUILDING 119

HABS No. WI-381-A-3

Page 3

are 37" wide x 35" tall, while those on the east facade that flank the wall chimney are 49" x 59½". All remaining windows are 37" x 51".

B. Doorways: All doors are metal replacements. Those in original openings are topped with 5½" thick wood lintels and feature red brick surrounds. The double doorway on the west (main) facade measures 67" x 80½" and is outfitted with wood infill and a single replacement door. The original doorways on the north and south facades are 40" x 81". The doorway that replaced a window on the north facade is 40" x 78".

7. Chimney: A wall chimney constructed of tan, glazed tile with red brick accents at the corners is centered on the east gabled endwall. It is 50" wide and projects 11". Two metal ash cleanout doors (10½" square) are at the bottom. The chimney's top portion has been replaced with red brick and is crowned by a concrete cap pierced by two square tile flues.

C. Interior Description:

- A. General Description: The east end of the building originally contained a kitchen. The rest of the building was occupied by an open dining hall. The mess hall has been converted into private-room barracks. No original fabric remains.

D. Setting:

Building 119 is a component of the 127th Infantry Regiment Cantonment Area Subcomplex, which also includes Building 117 (HABS WI-381-A-1), Building 118 (HABS WI-381-A-2), Building 120 (HABS WI-381-A-4), Building 121 (HABS WI-381-A-5), Building 122 (HABS WI-381-A-6), Building 123 (HABS WI-381-A-7), Building 124 (HABS WI-381-A-8), Building 125 (HABS WI-381-A-9), Building 126 (HABS WI-381-A-10), Building 127 (HABS WI-381-A-11), Building 128 (HABS WI-381-A-12), Building 129 (HABS WI-381-A-13), Building 130 (HABS WI-381-A-14), Building 131 (HABS WI-381-A-15) and Building 132 (HABS WI-381-A-16). Additional components of the general Camp Williams complex include the 128th Infantry Regiment Cantonment Area (HABS WI-381-B) and the former Officer's Club and present day museum (HABS WI-381-C).

Sources: Citations for all sources in common with the 127th Subcomplex are provided in the "Sources" section of Subcomplex's overview document (HABS No. WI-381-A). Two additional sources were used and are cited below.

CAMP WILLIAMS

127TH INFANTRY REGIMENT CANTONMENT AREA SUBCOMPLEX-BUILDING 119

HABS No. WI-381-A-3

Page 4

“New Mess Halls at Camp Williams,” *Wisconsin National Guard Review* 17:3 (May 1940).

Photographs of the WMA at Camp Williams, circa 1958, Located in Camp Williams Files, Facilities Management Office, Department of Military Affairs, Madison, WI.

Historians: Brian J. Faltnson, M.A., Principal Investigator, and John N. Vogel, Ph.D., Project Director, Heritage Research, Ltd., 2009.