

Mission San José de Tumacacori
Tumacacori National Monument, NEAR TUBAC
Santa Cruz County, Arizona

HABS No. ARIZ-3

HABS
ARIZ
12-TUBA.V

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Arizona

Historic American Buildings Survey
Prepared at Headquarters Office for
District of Arizona

MISSION SAN JOSÉ DE TUMACACORI
Tumacacori National Monument, Santa Cruz County, Arizona
TUBAC VICINITY

Owner: U. S. Government, National Park Service.

Date of Erection: Circa 1791 (Mission founded in 1691).

Architect: Not known.

Builders: Franciscan Fathers, probably with Indian labor.

Present Condition: Ruinous. Partly restored. Protected by restored roof.

Number of Stories: One, tower (part), choir loft (destroyed).

Materials of Construction: Walls adobe brick, plastered inside and outside. Hard burned brick used in arches, dome, mouldings, and part of exterior face of mortuary chapel. Earth floor.

Other Existing Records: National Park Service, Southwestern Monuments, Special Report No. 15 (Archeological Survey, 1934). Drawing, 1864, in "Adventures in Apache County", J. Ross Browne.

Additional Data: From mimeographed bulletin of National Park Service, August 1938.

"This monument embraces 10 acres of land in Santa Cruz County, Arizona, about 49 miles south of Tucson and 19 miles north of Nogales. It was created September 15, 1908. Upon the tract is located an ancient Spanish ruin, the Mission San Jose de Tumacacori, founded by the Jesuit priest, missionary, and explorer, Father Eusebio Francisco Kino, about 1691. The Sobaipuri Indians, who lived in the vicinity at that time, appear to have merged later with the Papago tribe.

"After the year 1768 priests belonging to the order of Franciscan Fathers took charge of the mission....In the early part of the nineteenth century the mission was attacked by Apache Indians, who drove the priests away and disbanded the peaceable

Papago Indians residing in the vicinity of the mission. When found by Americans, about the year 1850, the mission was in a condition of ruin.

"The ruins as they stand consist of the walls and tower of an old church building, the walls of a mortuary chamber at the north end of the church building, and the remains of a court or churchyard, and the remnants of three of the accessory buildings.

"The walls of the church building are 6 feet thick, built of adobe and plastered both inside and outside with lime mortar. The inside walls of the main church building received two coats of this plaster, a first or inner coat being of a rather coarse character and the finishing coat being of a very fine, hard, and lasting type. The dome over the sanctuary, the sacristy roof, and the belfry tower, are constructed of burned brick, this being one of the characteristics of the architecture of the mission, in which respect the construction differs from many other early Spanish missions. Inside, the dimensions of the church are 18 feet wide by 75 feet in length. The part used for the altar is situated at the north end. It is 18 feet square, surmounted with a circular dome, finished on the inside with white plaster decorated or frescoed in colors. The plaster and decorations are in a good state of preservation, but the original altar is entirely gone. The altar now existing was constructed by the local Mexicans, who used the church at times. To the east of the sanctuary there is the sacristy, 16 by 20 feet, 20 feet high, covered with a barrel-vaulted roof built of burned brick. The sanctuary and sacristy are the only parts of the mission having the original roofs. In the south end of the church there was a choir loft carried on an arch. This loft and arch are now broken down. The outside wall of the north end of the church building is faced with white plaster studded at regular intervals with decorative clusters made of fragments of broken slag and broken brick.

"About 25 feet north of the church building, and in the center of the churchyard, there is a circular mortuary chamber. The wall is $3\frac{1}{2}$ feet thick by 16 feet high, built of adobe, surmounted on the top with a row of ornamental cornice brick (made of burned brick). The chamber has one entrance. The walls were originally decorated on the outside with white plaster studded with fragments of red brick.

"The entrance to the church is at the south and has an arched doorway. To the east of the entrance there is a room, about 10 feet square, with a winding stairway inside leading up to the belfry. Access to the belfry is gained by means of this old stairway. This room is surmounted by the belfry tower, which is constructed of burned brick. The walls supporting the tower are adobe. Through action of the elements, the church, appurtenant buildings, and inclosing walls were in a very bad state of ruin when the monument

was created. Most of the roofs had long since fallen in and portions of the main building had become undermined. Since that time as rapidly as limited funds have permitted the mission has been placed under roof and in good state of preservation by Superintendent Pinkley, of Southwestern National Monuments.

"The restoration of the double doors between the sanctuary and sacristy was an especially interesting piece of work. The original doors were torn out and carried away many years ago, and it was impossible to find anyone who could describe them from personal observation. Picks and bars had been used to tear out the old frame, with resultant destruction to the surrounding plastering, and all that was left to start with was a gaping hole in the wall. The wall of this place, however, was some 6 feet thick, with an arched opening carried from the square frame of the doorway on through to the sacristy side, and the original south door of the double doors, in swinging back into this arched opening, had made a small mark in the plaster. This mark was about 2 inches long and a quarter of an inch deep, and was quite clearly cut by the upper and outer corner of the original door. From this the size of the doors and width and thickness of the frames were figured out. The details of the doors, such as number and placing of panels, etc., had to be guessed at, but in this the doors of the San Xavier Mission, which had been built a little earlier than those of the Tumacacori, and probably by the same workmen, were used as a guide. The doors were made of Spanish cedar, with the aid of a Mexican carpenter. No nails were used, the stiles and rails being mortised together and held with wedges driven home in the tenons. Six hinges were needed, and these were made in a nearby blacksmith's shop from old quarter-inch wagon tires. When the doors were completed and hung in place it was found that the outer and upper corner of the south door, when swung open, fitted into the little broken place in the plaster of the arch which had been made by the original door. After the doors were in place the broken places in the wall around the door frame were filled in with mortar and the doors and frame stained with a mixture of crude oil and gasoline to take off the new look.

"In the work of restoration of the Mission Superintendent Pinkley has had financial assistance from the Arizona State Legislature, the Chambers of Commerce of Tucson and Nogales, and other organizations. In its present condition the mission is equally as interesting as any of the famed California missions, and is historically important to the student of the early history of the State."

See also: Bolton, "Rim of Christendom".

Approved: John P. Orville

Date: Mar. 1939.

Mission San Jose de Tumacacori
Tumacacori National Monument
Tubac vicinity, Arizona

HABS No. ARIZ-3

(data page 4)

HABS
ARIZ.
12-TUBA.V
1.
no neg.



TUMACACORI 1864

Copy from drawing in "Adventures in Apache Country"
by J. Ross Browne

Church of San Jose de Tumacocori
Tubac vicinity
Santa Cruz County
Arizona

Historic American Buildings Survey

AZ-3

Addendum

HABS,
ARIZ,
12 TUBA.V,
1-

REDUCED DRAWINGS

ADDENDUM TO:
SAN JOSE DE TUMACACORI (MISSION, RUINS)
Tumacacori National Historical Park
Tubac vicinity
Santa Cruz County
Arizona

HABS AZ-3
HABS ARIZ, 12-TUBA.V, 1-

FIELD RECORDS

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
1849 C Street NW
Washington, DC 20240-0001