

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPH

HAER
CAL,
34-ISLE,
1-

Sacramento River Bridge
Spanning the Sacramento River south of Locke
Isleton
Sacramento County
California

HAER No. CA-55

Jet Lowe, HAER staff photographer c. 1983

CA-55-1

VIEW OF DOUBLE BASCULE BRIDGE BUILT IN 1923

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
CAL,
34-ISLE,
1-

HAER No. CA-55

ADDENDUM TO
SACRAMENTO RIVER BRIDGE
Spanning the Sacramento River South of Locke
Isleton
Sacramento County
California

CA-55-1 was transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jet Lowe, Photographer, 1983

CA-55-2 (CT) VIEW OF DOUBLE BASCULE BRIDGE BUILT IN 1923

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER CA-55

ISLETON BRIDGE

(Bridge No. 24-51)

Spanning Sacramento River at Post Mile 5.95 of California State

Highway 160

Isleton

Sacramento County

California

ADDENDUM TO:

SACRAMENTO BRIDGE

Spanning the Sacramento River south of Locke

Isleton

Sacramento County

California

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Photographs HAER CA-55-1 through HAER CA-55-2 were previously transmitted to the Library of Congress.

23 photographs were removed and placed in the field notes because they were copy negatives that were photocopied backwards.

CA-55-3 Copy negative of aerial photograph. Original photograph located in California Department of Transportation (CALTRANS) Engineering Services Division, Structure Design Services & Earthquake Engineering, Office of Photogrammetry, Sacramento, California. General Contextual view of bridge in relationship to its surrounding environment; aerial view taken from above

Don Tateishi, photographer, August 2004

CA-55-4 General view of north side of bridge, view looking southwest from eastern back of Sacramento River

Ed Anderson, photographer, November 2002

CA-55-5 General view of north side of bridge, view looking southeast from western bank of Sacramento River

CA-55-6 General view of south side of bridge, view looking northwest from eastern bank of Sacramento River

CA-55-7 General view of east side of bridge, view of east concrete approach portal, looking west

- CA-55-8 Copy negative of photograph. General view of west side of bridge, view of west concrete approach portal, looking east
- CA-55-9 General view looking northwest, view of structural elements, concrete and steel trusses
- CA-55-10 General view of structural elements, concrete framing and trusses, looking northwest from the southeastern bank of Sacramento River

Don Tateishi, photographer, May 2004

- CA-55-11 General view of structural elements, east concrete counterweight, concrete piers and steel framing and trusses, looking northwest from the southeastern bank of Sacramento River
- CA-55-12 General view of structural elements, west concrete counterweight and steel trusses, looking northeast from the west bank of Sacramento River

Don Tateishi, photographer, August 2004

- CA-55-13 Detail view of structural elements, west concrete counterweight, looking west from top of west bascule

Ed Anderson, photographer, November 2002

- CA-55-14 General view of structural elements, concrete deck, traffic gates down, looking west across bridge

Photographer unknown

- CA-55-15 General view of structural elements, steel deck, looking east

Don Tateishi, photographer, May 2004

- CA-55-16 General view of structural elements, view of deck from top of west bascule, looking east

Ed Anderson, photographer, November 2002

- CA-55-17 Detail view of substructure, concrete girder spans, underside and concrete pier, looking west
- CA-55-18 Detail view of east end abutment, looking southeast

Don Tateishi, photographer, May 2004

CA-55-19 Detail view of concrete piers, looking southwest from northeast bank of Sacramento River

Ed Anderson , photographer, November 2002

CA-55-20 Detail view of eastern span concrete railing and concrete truss, looking northwest. Note the traffic signals in the foreground at right

Don Tateishi, photographer, August 2004

CA-55-21 General view looking northwest, east end concrete approach and wing wall

Ed Anderson, photographer, November 2002

CA-55-22 General view looking northwest from west bank of Sacramento River, view of west end concrete wing wall, abutment, concrete girder span, and understructure

Don Tateishi, photographer, August 2004

CA-55-23 Detail view of timer wheel guards, steel railings and trusses on west span of bridge, looking northeast. Note the traffic gate in foreground at left

CA-55-24 Detail view of fuel tank, looking southwest

CA-55-25 Detail view of fog bell, looking north

CA-55-26 Detail view of air horns, looking northeast

CA-55-27 Detail view of plaque on south side, looking north, which reads "AMERICAN BRIDGE COMPANY U.S.A. 1922"

CA-55-28 Detail view of plaque on southeast approach portal, looking south, which reads "ISLETON BRIDGE 1923 SACRAMENTO COUNTY BOARD OF SUPERVISORS"

CA-55-29 General view looking southeast from west bank of Sacramento River, view of bridge control operator's house

CA-55-30 General view of east facade of bridge control operator's house, looking west from east bank of Sacramento River

CA-55-31 General view of south facade of bridge control operator's house, looking northwest

CA-55-32 General view of south facade of bridge control operator's house, looking north

CA-55-33 General view of east facade of bridge control operator's house, looking west from walkway on east side

- CA-55-34 General view of west facade of bridge control operator's house, looking east from plank on north side of bridge
- CA-55-35 Detail view of architectural elements, view of door on east corner of south facade, looking north
- CA-55-36 Detail view of architectural elements, view of windows on south facade of bridge control operator's house, looking north
- CA-55-37 General view of interior of bridge control operator's house, west half of interior looking west from center of control house
- CA-55-38 General view of interior of bridge control operator's house, east half of interior, looking east from center of control house
- CA-55-39 Detail view of engine generator, interior of bridge control operator's house, looking southwest
- CA-55-40 Detail view of air compressor, exterior of bridge control operator's house, looking north
- CA-55-41 Detail view of electrical panel, interior bridge control operator's house, looking west

Don Tateishi, photographer, May 2004

- CA-55-42 Detail view of bridge controls, interior of bridge control operator's house, looking west

Don Tateishi, photographer, August 2004

- CA-55-43 General contextual view of gear house located above west bascule, looking west from center of bridge
- CA-55-44 General view of east facade of gear house located above west bascule, looking west. View shows stairway leading to gear house, window detail and repairs on counterweight