

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MO,  
37-GASC.V,  
12 -

Kotthoff-Weeks Farm, Barn  
County Route J, .6 of a mile west of intersection  
with State Route 100, then .7 of a mile north  
on gravel road to farm entrance  
Gasconade Vicinity  
Gasconade County  
Missouri

HABS No. MO-248-C

Jet Lowe, Photographer April - May 1983

- MO-248-C-1 RECENTLY CLAPBOARDED WEST WALL
- MO-248-C-2 NORTHEAST CORNER
- MO-248-C-3 EAST FRONT
- MO-248-C-4 SOUTH END
- MO-248-C-5 EAST DOORWAY
- MO-248-C-6 THRESHING FLOOR, LOOKING SOUTH
- MO-248-C-7 FRAMING OF WEST DOORS
- MO-248-C-8 FRAMING AT NORTH END OF THRESHING FLOOR
- MO-248-C-9 DETAIL OF FRAMING AT NORTH END OF THRESHING FLOOR
- MO-248-C-10 CLOSE DETAIL OF SAME, SHOWING ASSEMBLY CODE MARKS
- MO-248-C-11 NORTH END OF HAYLOFT
- MO-248-C-12 FRAMING OF EAST WALL
- MO-248-C-13 DETAIL OF FRAMING IN SOUTHEAST CORNER
- MO-248-C-14 PART OF FRAMING OVER THRESHING FLOOR
- MO-248-C-15 GENERAL VIEW OF FRAMING OVER THRESHING FLOOR
- MO-248-C-16 LIVESTOCK STALLS

Clayton Fraser, Photographer July 1975

- MO-248-C-17 EAST FRONT BEFORE RECENT CLAPBOARDING
- MO-248-C-18 SOUTHEAST CORNER BEFORE RECENT CLAPBOARDING
- MO-248-C-19 DETAIL OF EAST WALL BEFORE RECENT CLAPBOARDING
- MO-248-C-20 NORTHWEST CORNER BEFORE RECENT CLAPBOARDING
- MO-248-C-21 SOUTH END BEFORE RECENT CLAPBOARDING