

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
VA,  
99-JACFR.V,  
1-

JACKSON'S FERRY BRIDGE  
(Bridge No. 1017)  
Route 52 over the New River,  
6.3 miles south of Route 94  
Jackson's Ferry vicinity  
Wythe County  
Virginia

HAER No. VA-113

Photographer: Rob Tucher

April 1995

- VA-1234-1 GENERAL VIEW OF WEST ELEVATION, LOOKING EAST
- VA-1234-2 GENERAL VIEW IN CONTEXT, LOOKING SOUTH
- VA-1234-3 APPROACH FROM NORTH, LOOKING SOUTHEAST
- VA-1234-4 APPROACH AND PORTAL VIEW FROM SOUTH, LOOKING NORTH
- VA-1234-5 EAST ELEVATION OBLIQUE, LOOKING SOUTHEAST
- VA-1234-6 WEST ELEVATION OBLIQUE, LOOKING SOUTHWEST
- VA-1234-7 EAST ELEVATION OBLIQUE OF CANTILEVER SPANS, LOOKING NORTHWEST
- VA-1234-8 WEST ELEVATION OF APPROACH SPAN No. 1, LOOKING EAST
- VA-1234-9 WEST ELEVATION OF APPROACH SPAN No. 2, LOOKING EAST
- VA-1234-10 PORTAL FROM NORTH, LOOKING SOUTH
- VA-1234-11 PORTAL AND DECK FROM SOUTH, LOOKING NORTH
- VA-1234-12 DECK FROM NORTH, INCLUDING SHOT TOWER, LOOKING SOUTHWEST
- VA-1234-13 UNDERSIDE OF APPROACH SPAN No. 1, AND NORTH ABUTMENT, LOOKING NORTH
- VA-1234-14 UNDERSIDE OF APPROACH SPAN No. 2, AND PIER No. 1, LOOKING SOUTH

INDEX TO PHOTOGRAPHS  
JACKSON'S FERRY BRIDGE  
(Bridge No. 1017)  
HAER No. VA-113 (Page 2)

- VA-1234-15 UNDERSIDE OF SUSPENDED SPAN AND NORTH CANTILEVER ARM, LOOKING NORTH
- VA-1234-16 PIER No. 4 AND UNDERSIDE OF NORTH CANTILEVER ARM, LOOKING NORTH
- VA-1234-17 SOUTH CANTILEVER ANCHOR ARM SUPERSTRUCTURE, LOOKING NORTH
- VA-1234-18 DETAIL OF SOUTH CANTILEVER ANCHOR ARM UPPER LATERAL BRACING AND CHORD CONNECTIONS
- VA-1234-19 DETAIL OF SOUTH CANTILEVER ANCHOR ARM UPPER CHORD AND ENDPOST CONNECTION U-19, LOOKING SOUTHWEST
- VA-1234-20 DETAIL OF SOUTH CANTILEVER ANCHOR ARM UPPER CHORD, POST, AND DIAGONAL CONNECTION U-17, LOOKING NORTHWEST
- VA-1234-21 DETAIL OF SOUTH CANTILEVER ARM CONNECTION U-15 AND U-16, LOOKING SOUTHWEST
- VA-1234-22 DETAIL OF SUSPENDED SPAN PIN CONNECTION U-12, LOOKING WEST
- VA-1234-23 DETAIL OF APPROACH SPAN No. 1 PORTAL AND CONNECTION U-1, LOOKING SOUTHWEST
- VA-1234-24 DETAIL OF APPROACH SPAN No. 1 UPPER CHORD CONNECTION U-2, LOOKING NORTHWEST
- VA-1234-25 DETAIL OF SOUTH CANTILEVER ANCHOR ARM CONNECTION L-1 AND LINK EXPANSION BEARING, LOOKING SOUTHEAST
- VA-1234-26 DETAIL OF SOUTH CANTILEVER FIXED BEARING AT PIER No. 5 AND CONNECTION L-16, LOOKING NORTHEAST
- VA-1234-27 DETAIL OF DECK JOINT BETWEEN APPROACH SPAN No. 3 AND NORTH CANTILEVER ANCHOR ARM AND RESPECTIVE BEARINGS AT PIER No. 3, LOOKING EAST

INDEX TO PHOTOGRAPHS  
JACKSON'S FERRY BRIDGE  
(Bridge No. 1017)  
HAER No. VA-113 (Page 3)

- VA-1234-28 DETAIL OF DECK JOINT BETWEEN APPROACH SPANS No. 1 AND No. 2 AT PIER No. 1, LOOKING EAST
- VA-1234-29 DETAIL OF SOUTH CANTILEVER ANCHOR ARM LOWER CHORD CONNECTION L-18, LOOKING NORTHEAST
- VA-1234-30 DETAIL OF SOUTH CANTILEVER ANCHOR ARM LOWER CHORD CONNECTION L-17, LOOKING EAST
- VA-1234-31 DETAIL OF SOUTH CANTILEVER ARM CONNECTION L-13, SHOWING SUSPENSION MEMBER AND PIN CONNECTION TO THE SUSPENDED TRUSS SPAN, LOOKING NORTHWEST
- VA-1234-32 DETAIL OF APPROACH SPAN No. 2 LOWER CHORD AND DIAGONAL CONNECTION L-2, LOOKING EAST