

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

San Carlos Irrigation Project,
Sacaton Dam and Bridge
Gila River, T4S R6E S12/13
~~Sacaton Vicinity~~ COOLIDGE
Pinal County
Arizona

AZ-50-D

HAER
ARIZ

11-COOL,
ID-

Bob Knotts, Photographer, June 1995

- AZ-50-D-1 DOWNSTREAM SIDE OF DAM AND BRIDGE TAKEN FROM
NORTH END
- AZ-50-D-2 UPSTREAM SIDE OF DAM AND BRIDGE WITH ABANDONED SAN
TAN FLOOD-WATER HEADGATE IN FOREGROUND. TAKEN FROM
NORTH END OF DAM
- AZ-50-D-3 VIEW OF UPSTREAM FACE OF BRIDGE AND DAM TAKEN FROM
NORTH END
- AZ-50-D-4 VIEW LOOKING ACROSS BRIDGE FROM SOUTH END
- AZ-50-D-5 SOUTH END CANAL BRIDGE WITH CANAL INTAKE GATE
STRUCTURE BEHIND
- AZ-50-D-6 SOUTH END OPERATING HOUSE AND INLET GATES TO SIPHON.
VIEW LOOKING WEST
- AZ-50-D-7 NORTH END CANAL BRIDGE ACROSS SAN TAN FLOOD-WATER
CANAL. VIEW LOOKING EAST
- AZ-50-D-8 ROADWAY ON NORTH END CANAL BRIDGE. VIEW LOOKING
NORTHWEST
- AZ-50-D-9 PLAQUE AT NORTH END OF DAM
- AZ-50-D-10 Photographic copy of photograph. (Source: U.S. Department of Interior.
Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal
Year 1919. Vol. I, RG 75, Entry 655, Box 25, National Archives,
Washington, D.C.) Photographer unknown. SACATON DAM SITE
LOOKING SOUTH SHOWING HEADWORKS OF SAN TAN FLOOD-
WATER CANAL

San Carlos Irrigation Project,
Sacaton Dam and Bridge
HAER No. AZ-50-D
Index to Photographs (page 2)

- AZ-50-D-11 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE SITE FROM QUARRY HILL, 10/1/24
- AZ-50-D-12 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE FROM QUARRY HILL, PRACTICALLY COMPLETED, 6/18/25
- AZ-50-D-13 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, CONSTRUCTION OF MAIN APRON, 12/9/24
- AZ-50-D-14 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, CONSTRUCTION BRIDGE PIERS
- AZ-50-D-15 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, CONSTRUCTION BRIDGE DECK, 4/5/25
- AZ-50-D-16 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National

San Carlos Irrigation Project ,
Sacaton Dam and Bridge
HAER No. AZ-50-D
Index to Photographs (page 3)

Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, SHOWING WEIR APRONS AND BRIDGE, 6/18/25.

- AZ-50-D-17 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, CONSTRUCTION OF WEIR, 1/17/25
- AZ-50-D-18 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, SOUTH END SLUICeway, INTAKE CANAL BRIDGE, OPERATING HOUSE, AND MAIN BRIDGE, 6/18/25
- AZ-50-D-19 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. SACATON DAM AND BRIDGE, CANAL BRIDGE, OPERATING HOUSE AND INTAKE, SOUTH END, 2/14/25
- AZ-50-D-20 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1926. Vol. I, Narrative and Photographs, RG 75, Entry 655, Box 29, National Archives, Washington DC.) Photographer unknown. SACATON DAM, BRIDGE FROM SOUTH END, 8/29/25
- AZ-50-D-21 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1926. Vol. I, Narrative and Photographs, RG 75, Entry 655, Box 29, National Archives, Washington DC.) Photographer unknown. SACATON DAM, UPSTREAM SIDE FROM SOUTH END, 8/29/25

San Carlos Irrigation Project,
Sacaton Dam and Bridge
HAER No. AZ-50-D
Index to Photographs (page 4)

- AZ-50-D-22 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1926. Vol. I, Narrative and Photographs, RG 75, Entry 655, Box 29, National Archives, Washington DC.) Photographer unknown. SACATON DAM, SOUTH END WITH CANAL AND ROADWAY, 8/29/25
- AZ-50-D-23 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1926. Vol. I, Narrative and Photographs, RG 75, Entry 655, Box 29, National Archives, Washington DC.) Photographer unknown. SACATON DAM, NORTH SIDE SIPHON AND INTAKE GATES, 2/23/26
- AZ-50-D-24 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1928. Vol I. Irrigation District #4, California and Southern Arizona, RG 75, BIA-Phoenix, Box 40, National Archives, Pacific Southwest Region) Photographer unknown. SACATON DAM, CONDUIT ANCHORING AND REINFORCING STEEL, APRIL 10, 1928
- AZ-50-D-25 Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1928. Vol I. Irrigation District #4, California and Southern Arizona, RG 75, BIA-Phoenix, Box 40, National Archives, Pacific Southwest Region.) SACATON DAM SHOWING CONSTRUCTION OF CONDUIT AND EXCAVATION OF GRAVEL, APRIL 10, 1928
- AZ-50-D-26 Photographic copy of construction drawing, dated August 1922, corrected 4/6/1925, in the possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. PLAN OF DAM AND GUIDE BANK
- AZ-50-D-27 Photographic copy of construction drawing, dated August 1922, corrected 4/8/1925, in the possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. SLUICEWAY AND HEADGATES, SOUTH ABUTMENT
- AZ-50-D-28 Photographic copy of construction drawing, dated 3/22/1923, corrected 4/8/1925, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. SECTIONS OF SOUTHSIDE INTAKE

San Carlos Irrigation Project ,
Sacaton Dam and Bridge
HAER No. AZ-50-D
Index to Photographs (page 5)

- AZ-50-D-29 Photographic copy of construction drawing, dated April 1923, corrected 4/6/1925, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. PIER DETAILS
- AZ-50-D-30 Photographic copy of construction drawing, dated 11/19/1928, corrected 4/8/1925, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. ELEVATION AND SECTIONS BRIDGE SPAN
- AZ-50-D-31 Photographic copy of construction drawing, no date, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. Untitled. DETAIL OF BRIDGE SPAN AND LAMP POST.
- AZ-50-D-32 Photographic copy of construction drawing, dated 4/28/1925, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. CANAL SPAN
- AZ-50-D-33 Photographic copy of construction drawing, dated 4/1925, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. CONSTRUCTION CAMP
- AZ-50-D-34 Photographic copy of construction drawing, dated 11/30/1927, approved 12/29/1927, in possession of SCIP Office, Coolidge, AZ. United States Indian Service, Irrigation. PROPOSED CONDUIT