

ST. MARY'S SEMINARY
600 N. Paca Street
Baltimore
Maryland

HABS No. MD-47

HABS
MD,
4-BALT,
18-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

Handwritten notes:
1938
1939

HABS
MD,
4-BALT
18-

HISTORIC AMERICAN BUILDINGS SURVEY

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

ST. MARY'S SEMINARY
600 N. Paca Street
Baltimore
Maryland

HABS No. MD-47

INVENTORY OF PHOTOGRAMMETRIC IMAGES

The glass photogrammetric plates listed below are not reproducible except with special permission. However, reference prints and film copy negatives have been made from the plates indicated by an asterisk (*) and are included in the Library of Congress collection of formal HABS/HAER photographs.

- 15 5" x 7" glass plate negatives (7 stereopairs and one single plate) produced by Perry E. Borchers of the Ohio State University in 1974.

One survey control contact print per plate; survey control information for each pair and for the single plate.

LC-HABS-GS05-B-1974-801L *	EAST AND NORTH FACADES FROM NE, ANGLED--INCLINED
LC-HABS-GS05-B-1974-801R	EAST AND NORTH FACADES FROM NE, ANGLED--INCLINED
	Left and right overlap: 95%
LC-HABS-GS05-B-1974-802L *	EAST FACADE, SOUTH PAVILION, FRONTAL--LEVEL
LC-HABS-GS05-B-1974-802R	EAST FACADE, SOUTH PAVILION, FRONTAL--LEVEL
	Left and right overlap: 80%

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 2)

LC-HABS-GS05-B-1974-803L	EAST FACADE, SOUTH PAVILION, FRONTAL--INCLINED
LC-HABS-GS05-B-1974-803R *	EAST FACADE, SOUTH PAVILION, FRONTAL--INCLINED Left and right overlap: 80%
LC-HABS-GS05-B-1974-804L *	CENTRAL PORTION OF WEST (REAR) FACADE, FRONTAL--INCLINED
LC-HABS-GS05-B-1974-804R	CENTRAL PORTION OF WEST (REAR) FACADE, FRONTAL--INCLINED Left and right overlap: 90%
LC-HABS-GS05-B-1974-805L	WEST FACADE, FRONTAL, DISTANT--LEVEL
LC-HABS-GS05-B-1974-805R *	WEST FACADE, FRONTAL, DISTANT--LEVEL Left and right overlap: 90%
LC-HABS-GS05-B-1974-806L	WEST FACADE, ANGLED, DISTANT--LEVEL
LC-HABS-GS05-B-1974-806R *	WEST FACADE, ANGLED, DISTANT--LEVEL Left and right overlap: 85%
LC-HABS-GS05-B-1974-807L	MAIN ENTRANCE IN EAST FACADE, ANGLED--INCLINED
LC-HABS-GS05-B-1974-807R *	MAIN ENTRANCE IN EAST FACADE, ANGLED--INCLINED Left and right overlap: 90%
LC-HABS-GS05-B-1974-808 *	SOUTH FACADE OF NW WING, ANGLED--INCLINED (Single plate)

12 9.5" x 9.5" glass plate diapositives (6 stereopairs)
produced by Perry Borchers of the Ohio State University in
1974.

One survey control contact print per plate; survey control
information for each plate.

LC-HABS-GS01-B-1974-809L	CENTRAL PORTION OF EAST FACADE, FRONTAL--LEVEL
LC-HABS-GS01-B-1974-809R *	CENTRAL PORTION OF EAST FACADE, FRONTAL--LEVEL Left and right overlap: 94%
LC-HABS-GS01-B-1974-810L *	STAIRWAY & MAIN ENTRANCE OF EAST FACADE, FRONTAL--LEVEL
LC-HABS-GS01-B-1974-810R	STAIRWAY & MAIN ENTRANCE OF EAST FACADE, FRONTAL--LEVEL Left and right overlap: 80%
LC-HABS-GS01-B-1974-811L	SOUTH FACADE, FRONTAL--LEVEL
LC-HABS-GS01-B-1974-811R *	SOUTH FACADE, FRONTAL--LEVEL Left and right overlap: 97%
LC-HABS-GS01-B-1974-812L *	NORTH FACADE OF SOUTH WING, GRAZING WEST FACADE, FRONTAL--LEVEL
LC-HABS-GS01-B-1974-812R	NORTH FACADE OF SOUTH WING, GRAZING WEST FACADE, FRONTAL--LEVEL Left and right overlap: 93%

LC-HABS-GS01-B-1974-813L * EASTERN PORTION OF NORTH FACADE,
FRONTAL--LEVEL

LC-HABS-GS01-B-1974-813R EASTERN PORTION OF NORTH FACADE,
FRONTAL--LEVEL

Left and right overlap: 94%

LC-HABS-GS01-B-1974-814L * EAST FACADE OF WEST WING PROJECTING FROM
NORTH FACADE, FRONTAL--LEVEL

LC-HABS-GS01-B-1974-814R EAST FACADE OF WEST WING PROJECTING FROM
NORTH FACADE, FRONTAL--LEVEL

Left and right overlap: 95%

62 2.25" x 2.25" film negatives (31 stereopairs) produced by
Perry E. Borchers of the Ohio State University in 1974.

One contact print per negative, mounted in pairs; survey
control information for each pair.

LC-HABS-FS13-B-1974-815L CORNICE AND ROOF AT SE CORNER,
INCLINED--ANGLED

LC-HABS-FS13-B-1974-815R * CORNICE AND ROOF AT SE CORNER,
INCLINED--ANGLED

Left and right overlap: 90%

LC-HABS-FS13-B-1974-816L CORNICE AND ROOF AT SOUTH END OF EAST
FACADE, INCLINED--FRONTAL

LC-HABS-FS13-B-1974-816R * CORNICE AND ROOF AT SOUTH END OF EAST
FACADE, INCLINED--FRONTAL

Left and right overlap: 92%

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 5)

LC-HABS-FS13-B-1974-817L * SOUTH END OF SOUTH PAVILION AT EAST FACADE,
UPPER PORTION--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-817R SOUTH END OF SOUTH PAVILION AT EAST FACADE,
UPPER PORTION--INCLINED, FRONTAL

Left and right overlap: 87%

LC-HABS-FS13-B-1974-818L * UPPER PORTION, CENTRAL CORNER OF SOUTH
PAVILION OF EAST FACADE--STRONGLY INCLINED,
FRONTAL

LC-HABS-FS13-B-1974-818R UPPER PORTION, CENTRAL CORNER OF SOUTH
PAVILION OF EAST FACADE--STRONGLY INCLINED,
FRONTAL

Left and right overlap: 91%

LC-HABS-FS13-B-1974-819L * UPPER PORTION, NORTH END OF SOUTH PAVILION
OF EAST FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-819R UPPER PORTION, NORTH END OF SOUTH PAVILION
OF EAST FACADE--INCLINED, FRONTAL

Left and right overlap: 90%

LC-HABS-FS13-B-1974-820L * CORNICE AND ROOF AT NE CORNER OF SOUTH
PAVILION OF EAST FACADE--INCLINED, ANGLED

LC-HABS-FS13-B-1974-820R CORNICE AND ROOF AT NE CORNER OF SOUTH
PAVILION OF EAST FACADE--INCLINED, ANGLED

Left and right overlap: 83%

LC-HABS-FS13-B-1974-821L * CORNICE AND ROOF AT SE CORNER OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, ANGLED

LC-HABS-FS13-B-1974-821R CORNICE AND ROOF AT SE CORNER OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, ANGLED

Left and right overlap: 95%

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 6)

LC-HABS-FS13-B-1974-822L

CORNICE AND ROOF AT SOUTH END OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-822R *

CORNICE AND ROOF AT SOUTH END OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, FRONTAL

Left and right overlap: 95%

LC-HABS-FS13-B-1974-823L

DORMER IN CENTER OF CENTRAL PAVILION OF EAST
FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-823R *

DORMER IN CENTER OF CENTRAL PAVILION OF EAST
FACADE--INCLINED, FRONTAL

Left and right overlap: 83%

LC-HABS-FS13-B-1974-824L *

CORNICE AND ROOF AT NE CORNER OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-824R

CORNICE AND ROOF AT NE CORNER OF CENTRAL
PAVILION OF EAST FACADE--INCLINED, FRONTAL

Left and right overlap: 83%

LC-HABS-FS13-B-1974-825L *

CORNICE AND ROOF AT SE CORNER OF NORTH
PAVILION OF EAST FACADE

LC-HABS-FS13-B-1974-825R

CORNICE AND ROOF AT SE CORNER OF NORTH
PAVILION OF EAST FACADE

Left and right overlap: 90%

LC-HABS-FS13-B-1974-826L *

CORNICE AND ROOF AT NE CORNER OF EAST
FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-826R

CORNICE AND ROOF AT NE CORNER OF EAST
FACADE--INCLINED, FRONTAL

Left and right overlap: 83%

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 7)

LC-HABS-FS13-B-1974-827L MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
NORMAL ANGLE

LC-HABS-FS13-B-1974-827R * MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
NORMAL ANGLE
Left and right overlap: 93%

LC-HABS-FS13-B-1974-828L * MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL

LC-HABS-FS13-B-1974-828R MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
Left and right overlap: 92%

LC-HABS-FS13-B-1974-829L BASEMENT WINDOW AND GRILLE SOUTH OF MAIN
ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
NORMAL ANGLE

LC-HABS-FS13-B-1974-829R * BASEMENT WINDOW AND GRILLE SOUTH OF MAIN
ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
NORMAL ANGLE
Left and right overlap: 86%

LC-HABS-FS13-B-1974-830L SE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST
FACADE--LEVEL, ANGLED NORMAL ANGLE

LC-HABS-FS13-B-1974-830R * SE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST
FACADE--LEVEL, ANGLED NORMAL ANGLE
Left and right overlap: 92%

LC-HABS-FS13-B-1974-831L * NE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST
FACADE--LEVEL, ANGLED NORMAL ANGLE

LC-HABS-FS13-B-1974-831R NE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST
FACADE--LEVEL, ANGLED NORMAL ANGLE
Left and right overlap: 98%

ST MARY'S SEMINARY
HABS No. MD-47
Data (Page 8)

LC-HABS-FS13-B-1974-832L * CENTRAL HEIGHT OF CENTRAL PAVILION IN EAST FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-832R CENTRAL HEIGHT OF CENTRAL PAVILION IN EAST FACADE--INCLINED, FRONTAL

Left and right overlap: 90%

LC-HABS-FS13-B-1974-833L * UPPER PORTION OF CENTRAL PAVILION IN EAST FACADE--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-833R UPPER PORTION OF CENTRAL PAVILION IN EAST FACADE--INCLINED, FRONTAL

Left and right overlap: 90%

LC-HABS-FS13-B-1974-834L UPPER PORTION OF EAST PAVILION ON SOUTH FACADE--INCLINED, SLIGHTLY ANGLED

LC-HABS-FS13-B-1974-834R * UPPER PORTION OF EAST PAVILION ON SOUTH FACADE--INCLINED, SLIGHTLY ANGLED

Left and right overlap: 95%

LC-HABS-FS13-B-1974-835L * SW CORNER OF EAST PAVILION ON SOUTH FACADE--INCLINED, ANGLED NORMAL ANGLE

LC-HABS-FS13-B-1974-835R SW CORNER OF EAST PAVILION ON SOUTH FACADE--INCLINED, ANGLED NORMAL ANGLE

Left and right overlap: 92%

LC-HABS-FS13-B-1974-836L * SW CORNER AND SOUTH FACADE--LEVEL, ANGLED, WIDE ANGLE

LC-HABS-FS13-B-1974-836R SW CORNER AND SOUTH FACADE--LEVEL, ANGLED, WIDE ANGLE

Left and right overlap: 100%

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 9)

LC-HABS-FS13-B-1974-837L * WEST FACADE OF SOUTH WING OF WEST
FACADE--SLIGHTLY INCLINED, SLIGHTLY ANGLED,
NORMAL ANGLE

LC-HABS-FS13-B-1974-837R WEST FACADE OF SOUTH WING OF WEST
FACADE--SLIGHTLY INCLINED, SLIGHTLY ANGLED,
NORMAL ANGLE

Left and right overlap: 80%

LC-HABS-FS13-B-1974-838L DORMER IN WEST FACADE OF SOUTH WING OF WEST
FACADE--STRONGLY INCLINED, ANGLED

LC-HABS-FS13-B-1974-838R * DORMER IN WEST FACADE OF SOUTH WING OF WEST
FACADE--STRONGLY INCLINED, ANGLED

Left and right overlap: 82%

LC-HABS-FS13-B-1974-839L CENTRAL PAVILION OF WEST FACADE--SLIGHTLY
ANGLED, FRONTAL, NORMAL ANGLE

LC-HABS-FS13-B-1974-839R * CENTRAL PAVILION OF WEST FACADE--SLIGHTLY
ANGLED, FRONTAL, NORMAL ANGLE

Left and right overlap: 98%

LC-HABS-FS13-B-1974-840L CORNICE AND DORMER OF CENTRAL PAVILION OF
WEST FACADE--INCLINED, ANGLED

LC-HABS-FS13-B-1974-840R * CORNICE AND DORMER OF CENTRAL PAVILION OF
WEST FACADE--INCLINED, ANGLED

Left and right overlap: 90%

LC-HABS-FS13-B-1974-841L * CORNICE AND DORMER OF SOUTH FACADE OF NW
WING--INCLINED, FRONTAL

LC-HABS-FS13-B-1974-841R CORNICE AND DORMER OF SOUTH FACADE OF NW
WING--INCLINED, FRONTAL

Left and right overlap: 93%

LC-HABS-FS13-B-1974-842L * BASE OF WEST FACADE OF NW WING--LEVEL,
FRONTAL WIDE ANGLE

LC-HABS-FS13-B-1974-842R BASE OF WEST FACADE OF NW WING--LEVEL,
FRONTAL WIDE ANGLE

Left and right overlap: 97%

LC-HABS-FS13-B-1974-843L WEST SIDE OF BAY AT NW CORNER OF BUILDING--
SLIGHTLY INCLINED, ANGLED, NORMAL ANGLE

LC-HABS-FS13-B-1974-843R * WEST SIDE OF BAY AT NW CORNER OF BUILDING--
SLIGHTLY INCLINED, ANGLED, NORMAL ANGLE

Left and right overlap: 90%

LC-HABS-FS13-B-1974-844L * NE CORNER OF BAY AT NW CORNER OF BUILDING--
LEVEL, ANGLED, WIDE ANGLE

LC-HABS-FS13-B-1974-844R NE CORNER OF BAY AT NW CORNER OF BUILDING--
LEVEL, ANGLED, WIDE ANGLE

Left and right overlap: 99%

LC-HABS-FS13-B-1974-845L * ROOF AND CORNICE AT NW CORNER OF EAST
PAVILION OF NORTH FACADE--INCLINED, ANGLED

LC-HABS-FS13-B-1974-845R ROOF AND CORNICE AT NW CORNER OF EAST
PAVILION OF NORTH FACADE--INCLINED, ANGLED

Left and right overlap: 92%

PROJECT INFORMATION STATEMENT

Photogrammetric images were incorporated into the HABS/HAER collections in the summers of 1985 and 1986. Inventories of the images were compiled and filed as data pages for each structure recorded. Since the glass photogrammetric plates are not reproducible except with special permission, a reference print and film copy negative were made from one plate of each stereopair and from the most informative plates in sequential sets. The reference prints and copy negatives were then incorporated into the formal HABS/HAER photograph collections.

ST. MARY'S SEMINARY
HABS No. MD-47
Data (Page 11)

The Photogrammetric Images Project was a cooperative endeavor between the HABS/HAER Division of the National Park Service and the Prints and Photographs Division of the Library of Congress. The reference prints and film copy negatives of the original plates were made by the Library of Congress Photoduplication Service with funds provided by the Library of Congress Flat Film Preservation Fund. Additional reproductions were made by HABS/HAER. The project was supervised by HABS/HAER Architect John A. Burns, AIA, and completed by HABS Historians Jeanne C. Lawrence (University of London) in 1985 and Caroline R. Alderson (Columbia University) in 1986.

Addendum to:
St. Mary's Seminary
600 N. Paca Street
Baltimore
Maryland

HABS No. MD-47-

HABS
MD.
4-BALT.
18-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

HABS
MD,
4-BALT,
18-

ARCHITECTURAL DATA FORM

STATE Maryland	COUNTY	TOWN OR VICINITY Baltimore
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) St. Mary's Seminary		HABS NO. MD-47
SECONOARY OR COMMDN NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LDCATION FOR RURAL SITES) 600 N. Paca St.		
OATE OF CONSTRUCTION (INCLUDE SOURCE) 1876-1878	ARCHITECT(S) (INCLUDE SOURCE) E. Francis Baldwin	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Oldest Roman Catholic seminary in U.S. Founded in 1791 by four French Supicians, the order that established the seminary concept in France in 1642.		
STYLE (IF APPROPRIATE) Second Empire		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick ; 1st story rock-faced stone limestone trim		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Four stories ; U-shaped with projecting central end pavilion		
EXTERIOR FEATURES OF NOTE Mansard roof; bracketed cornice; front center gable; main second story entrance with flanking columns; arched windows (rectangular and round)		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
MAJOR ALTERATIONS AND ADOITIONS WITH OATES		
PRESENT CONDITION AND USE Demolished c.1974.		
OTHER INFORMATION AS APPROPRIATE Continuously active in parochial educational system		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) 45 unplotted photogrammetric stereopairs are in the HABS collection. National Register		
COMPILER, AFFILIATION M. McDonald HABS Historian		OATE 8-1-84

ADDENDUM TO:
ST. MARY'S SEMINARY
600 North Paca Street
Baltimore
Independent City
Maryland

HABS MD-47
HABS MD,4-BALT,18-

FIELD RECORDS

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
1849 C Street NW
Washington, DC 20240-0001