

## HISTORIC AMERICAN ENGINEERING RECORD

### INDEX TO PHOTOGRAPHS

ADDENDUM TO:  
QUIGLEY CABIN  
Denali National Park & Preserve  
McKinley Station  
Denali Borough  
Alaska

HAER AK-40

Photographs HAER AK-40-1 and HAER AK-40-2 were previously transmitted to the Library of Congress.

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Todd A Croteau, photographer, 2014

AK-40-3	Contextual view from the road showing the front of the cabin with the shed at right.
AK-40-4	Front elevation of the cabin using a wide-angle lens.
AK-40-5	Front elevation of the cabin using a telephoto lens.
AK-40-6	3/4 view of the cabin showing the front and south side elevations.
AK-40-7	Detail of the front porch showing the log columns with a simple capitoll or abacus at the top. Note the gutter in the upper left.
AK-40-8	Detail of the roof eaves with the galvanized gutter. The writing on the gutter is the address for shipment of the gutter to the Quigleys.
AK-40-9	South side elevation.
AK-40-10	3/4 view of the south side and rear elevations showing the connected shed and detached shed at left.
AK-40-11	3/4 view of the south side and rear elevations showing the connected shed and detached shed at left.
AK-40-12	Rear elevation showing the attached shed structure at left.
AK-40-13	3/4 view of the rear and north elevations showing the attached shed on the rear.
AK-40-14	North side elevation showing the bump-out with the bedroom at right.
AK-40-15	Interior view looking northeast in the living area at the front of the cabin.
AK-40-16	Interior view looking northwest in the living area with the kitchen in the background.

QUIGLEY CABIN  
HAER AK-40  
INDEX TO PHOTOGRAPHS

- AK-40-17 Interior view looking southwest in the kitchen with the living area in the background.
- AK-40-18 Interior view looking northwest in the kitchen.
- AK-40-19 Interior view looking northeast in the bedroom.
- AK-40-20 Front elevation of the detached shed.
- AK-40-21 View of the outhouse located behind the cabin. The outhouse is in a collapsed state.