

SKAGWAY CITY HALL
350 Fifth Avenue
Skagway
Skagway
Alaska

HABS AK-243
HABS AK-243

REDUCED COPIES OF MEASURED DRAWINGS

FIELD RECORDS

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
1849 C Street NW
Washington, DC 20240-0001

ADDENDUM TO:
SKAGWAY CITY HALL
(Old City Hall)
350 Fifth Avenue
Skagway
Skagway
Alaska

HABS AK-243
HABS AK-243

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
FIELD RECORDS

HISTORIC AMERICAN BUILDINGS SURVEY
ALASKA REGIONAL OFFICE
National Park Service
U.S. Department of the Interior
240 West 5th Avenue, Room 114
Anchorage, AK 99501

HISTORIC AMERICAN BUILDINGS SURVEY

**SKAGWAY CITY HALL
(Old City Hall)**

HABS No. AK-243

Location: 350 Fifth Avenue, Municipality of Skagway Borough, Alaska

The building is located at latitude: 59.455963, longitude: -135.316102.
This point was obtained in June 2016 using Google Earth (WGS84).
There is no restriction on its release to the public.

Appendix A: Color Images



Fig. 1. Living room looking east to entry porch. Interior wall finish exposed to show heavy log construction. (Photographer: Robert Lyon, 2015)



Fig. 2. Living room fireplace looking north. (Photographer: Robert Lyon, 2015)



Fig. 3. Detail of fireplace grille. (Photographer: Robert Lyon, 2015)



Fig. 4. Dining room looking southeast. (Photographer: Robert Lyon, 2015)



Fig. 5. Kitchen looking east into utility room. (Photographer: Robert Lyon, 2015)



Fig. 6. Utility room looking northwest. (Photographer: Robert Lyon, 2015)



Fig. 7. North corner windows in bedroom. (Photographer: Robert Lyon, 2015)



Fig. 8. Rear attic space looking southwest to gable end of original building. Original window cut to door opening. (Photographer: Robert Lyon, 2015)



Fig. 9. Rear attic space looking east. (Photographer: Robert Lyon, 2015)



Fig. 10. Rear attic space looking northeast. (Photographer: Robert Lyon, 2015)