

HABS  
CONN,  
2 - BRIS,  
1 -  
(Page 1)

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Dr. William M. Curtis House  
23-25 High Street  
Bristol  
Hartford County  
Connecticut

HABS No. CT-430

Photographer (all views): Wayne Fleming

November 1989

- CT-430-1 FRONT (SOUTH) ELEVATION, VIEW NORTH
- CT-430-2 WEST-SIDE ELEVATION, VIEW NORTHEAST
- CT-430-3 EAST-SIDE AND REAR (NORTH) ELEVATIONS, VIEW SOUTHWEST
- CT-430-4 FRONT PORCH, DETAIL OF ORIEL AND MAIN ENTRY, VIEW NORTHEAST
- CT-430-5 FRONT PORCH, DETAIL OF SIDE ENTRY AND ORIEL, VIEW NORTH
- CT-430-6 WEST ELEVATION, DETAIL OF OVERHANGING STORY, ORIEL AND ELLIPTICAL LIGHTS
- CT-430-7 INTERIOR: FRONT HALL, SHOWING LIVING-ROOM COLUMNS, PANELED DOOR, LINCRUSTA WAINSCOTING, INTERIOR OF ORIEL, AND STAIRCASE RAILING, VIEW SOUTH
- CT-430-8 INTERIOR: FRONT HALL VIEWED FROM LIVING ROOM, SHOWING LIVING-ROOM COLUMNS, STAIRCASE RAILING AND PANELED SPANDREL, AND NICHE BELOW STAIRCASE, VIEW WEST
- CT-430-9 INTERIOR: FRONT HALL, CLOSE-UP OF STAIRCASE RAILING AND PANELING, VIEW SOUTHWEST
- CT-430-10 INTERIOR: NICHE BELOW STAIRS AND MIRROR FRAME, VIEW NORTHWEST

(continued)

Dr. William M. Curtis House  
HABS No. CT- 430  
Index to Photographs (Page 2)

- CT-430-11 INTERIOR: VIEW THROUGH DINING ROOM TO LIVING ROOM, VIEW SOUTH
- CT-430-12 INTERIOR: VIEW THROUGH LIVING ROOM TO DINING ROOM, VIEW NORTH
- CT-430-13 INTERIOR: LIVING ROOM, SHOWING TYPICAL DOUBLE-HUNG WINDOW (LEFT) AND FRONT PICTURE WINDOW (RIGHT), VIEW SOUTHEAST
- CT-430-14 INTERIOR: NORTHWEST CORNER OF LIVING ROOM, SHOWING COLUMNS SETTING ROOM OFF FROM HALL AND DINING ROOM, CORNER PILASTER, CORNICE TREATMENT, AND COFFERED CEILING; VIEW NORTHWEST
- CT-430-15 INTERIOR: LIVING ROOM, COFFERED CEILING, VIEW SOUTH
- CT-430-16 INTERIOR: DINING ROOM, DETAIL OF CORNER CABINET, VIEW NORTHEAST
- CT-430-17 INTERIOR: DINING ROOM, DETAIL OF CORNER FIREPLACE, VIEW NORTHWEST
- CT-430-18 INTERIOR: DINING ROOM, NORTH WALL, WITH FIREPLACE TO LEFT AND CABINET TO RIGHT, VIEW NORTH
- CT-430-19 INTERIOR: DINING ROOM, EAST WALL, WITH CABINET TO LEFT AND COLUMNS SETTING ROOM OFF FROM LIVING ROOM TO RIGHT, VIEW EAST
- CT-430-20 INTERIOR: DINING ROOM, COFFERED CEILING, VIEW NORTH
- CT-430-21 INTERIOR: SECOND-FLOOR BEDROOM, SHOWING TYPICAL CONDITION OF ALL SPACES EXCEPT LIVING ROOM, DINING ROOM AND HALL, VIEW SOUTHEAST

PHOTOGRAPHS, KEY PLAN

