

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
MCCORMICK APARTMENTS
(National Trust for Historic Preservation Headquarters)
1785 Massachusetts Avenue Northwest
Washington
District of Columbia

HABS DC-265

Photographs HABS DC-265-1 through HABS DC-265-5 were previously transmitted to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

William Lebovich, photographer, December 2013

DC-265-6	Massachusetts Avenue and 18th Street facades from roof of 1800 Massachusetts Avenue, looking northeast
DC-265-7	Massachusetts Avenue and 18th Street facades from ground level
DC-265-8	Entrance
DC-265-9	18th Street facade, looking from the roof of 1801 Massachusetts Avenue, looking east
DC-265-10	18th and P Street facades, looking southeast
DC-265-11	P Street facade, looking south
DC-265-12	P Street facade and alley, looking southeast
DC-265-13	P Street facade (partial) and alley facade
DC-265-14	Elevator door on alley facade
DC-265-15	Massachusetts Avenue facade (and Carnegie Building), looking northwest
DC-265-16	Massachusetts Avenue and 18th Street facades, looking north
DC-265-17	Massachusetts Avenue facade, primarily ground (basement) and first-story, looking east
DC-265-18	Massachusetts Avenue and 18th Street facades and roof
DC-265-19	Chimney, southeast corner of roof
DC-265-20	Roof, looking east along Massachusetts Avenue

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-21	Roof, looking north along 18th Street at stair housing, lightwells, vents and chimneys
DC-265-22	Roof, looking northeast
DC-265-23	Roof, looking north at chimneys along P Street facade
DC-265-24	Roof, looking south along alley, showing modern utility structure that fills the corner of the V-shaped alley wall
DC-265-25	Interior view, ground floor, Massachusetts Avenue wing, stairs boarded up at first-floor level
DC-265-26	Interior view, ground floor, 18th Street wing, Law Department, fourth office from entrance
DC-265-27	Interior view, ground floor, boiler room, elevator door to alley, visible at top of photograph
DC-265-28	Interior view, room 100, entrance (west) wall
DC-265-29	Interior view, room 100, north wall
DC-265-30	Interior view, room 100, close-up of fireplace, oval, and surround visible in HABS DC-265-29
DC-265-31	Interior view, room 100, close-up of fireplace, fireback and fireplace cheeks
DC-265-32	Interior view, room 100, east wall
DC-265-33	Interior view, room 100, angled close-up of stairs and surround visible in photograph HABS DC-265-32
DC-265-34	Interior view, room 100, south wall
DC-265-35	Interior view, room 100, ceiling
DC-265-36	Interior view, room 100, angled view from entrance
DC-265-37	Interior view, room 101, looking west towards front door
DC-265-38	Interior view, room 101, north wall
DC-265-39	Interior view, room 101, east wall
DC-265-40	Interior view, room 101, south wall
DC-265-41	Interior view, room 1S1, looking east
DC-265-42	Interior view, room 102, looking south
DC-265-43	Interior view, room 102, looking north
DC-265-44	Interior view, room 103, looking north, vault door at left
DC-265-45	Interior view, room 104, south wall
DC-265-46	Interior, room 104, close-up of fireplace visible in photograph HABS DC-265-45

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-47	Interior, room 104, west wall
DC-265-48	Interior, room 104, north wall
DC-265-49	Interior, room 104, east wall
DC-265-50	Interior, room 105, looking north
DC-265-51	Interior, room 105, angled close-up of north wall, showing closet
DC-265-52	Interior, room 105, east wall
DC-265-53	Interior, room 105, south wall, looking into room 104
DC-265-54	Interior, room 105, west wall
DC-265-55	Interior, room 106, south wall, looking from room 107
DC-265-56	Interior, room 106, south wall, close-up of fireplace
DC-265-57	Interior, room 106, west wall
DC-265-58	Interior, room 106, north wall
DC-265-59	Interior, room 106, east wall
DC-265-60	Interior, room 107, looking north
DC-265-61	Interior, room 107, close-up of fireplace visible in photograph HABS DC-265-60
DC-265-62	Interior, room 107, east wall
DC-265-63	Interior, room 107, looking south
DC-265-64	Interior, room 107, west wall
DC-265-65	Interior, room 108, west wall
DC-265-66	Interior, room 108, east wall
DC-265-67	Interior, room 108, north wall
DC-265-68	Interior, room 109, looking south
DC-265-69	Interior, room 109, looking north
DC-265-70	Interior, room 116, east wall
DC-265-71	Interior, room 117, east wall
DC-265-72	Interior, room 119, looking east
DC-265-73	Interior, room 119, stairs up to mezzanine, looking east
DC-265-74	Interior, mezzanine, room M102, looking east
DC-265-75	Interior, room 120, north and east walls
DC-265-76	Interior, room 120, north wall, fireplace, corrugated firebox
DC-265-77	Interior, room 121, looking west into room 120
DC-265-78	Interior, room 122, west wall

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-79	Interior, room 123, looking north
DC-265-80	Interior, room 201, looking east
DC-265-81	Interior, room 201, close-up of fireplace visible in photograph HABS DC-265-80
DC-265-82	Interior, room 201, looking northwest
DC-265-83	Interior, room 2S1, looking northwest
DC-265-84	Interior, room 2S1, looking northeast
DC-265-85	Interior, room 202, looking east
DC-265-86	Interior, room 203, looking west
DC-265-87	Interior, room 204, south wall
DC-265-88	Interior, room 204, west wall
DC-265-89	Interior, room 204, north and east walls
DC-265-90	Interior, room 205, looking northwest
DC-265-91	Interior, room 205
DC-265-92	Interior, room 205, close-up of rounded corner windows and fireplace
DC-265-93	Interior, room 205, west wall
DC-265-94	Interior, room 205, looking southeast
DC-265-95	Interior, room 205, looking northeast
DC-265-96	Interior, room 206, north wall
DC-265-97	Interior, room 206, east wall
DC-265-98	Interior, room 206, south wall
DC-265-99	Interior, room 206, west wall
DC-265-100	Interior, room 207, looking southwest
DC-265-101	Interior, room 207, looking northeast
DC-265-102	Interior, room 208, east wall
DC-265-103	Interior, room 209, looking east
DC-265-104	Interior, room 209, looking west
DC-265-105	Interior, room 210, looking north
DC-265-106	Interior, room 210, looking south
DC-265-107	Interior, room 211, looking north
DC-265-108	Interior, room 211, looking south
DC-265-109	Interior, room 212, south wall
DC-265-110	Interior, room 212, east wall

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-111	Interior, room 212, north wall
DC-265-112	Interior, room 212, west wall
DC-265-113	Interior, room 213, looking south
DC-265-114	Interior, room 214, looking northwest
DC-265-115	Interior, room 214, looking southeast
DC-265-116	Interior, room 215, looking north
DC-265-117	Interior, room 216, looking north
DC-265-118	Interior, room 216, looking south
DC-265-119	Interior, room 217, looking south
DC-265-120	Interior, room 218, east wall
DC-265-121	Interior, room 218, south wall
DC-265-122	Interior, room 218, west wall
DC-265-123	Interior, room 218, north wall
DC-265-124	Interior, room 219, looking east towards corridor and stairs to mezzanine
DC-265-125	Interior, room 219, looking west
DC-265-126	Interior, mezzanine, corridor, looking west
DC-265-127	Interior, mezzanine, room b, looking south
DC-265-128	Interior, room 223, looking south
DC-265-129	Interior, room 319 (west section), looking east towards corridor and mezzanine stairs
DC-265-130	Interior, room 319 (west section), looking east
DC-265-131	Interior, room 319 (east section), looking west
DC-265-132	Interior, room 419, looking east at corridor and stairs to mezzanine
DC-265-133	Interior, room 419, looking east
DC-265-134	Interior, room 501, looking north
DC-265-135	Interior, room 501, looking north, skylight panels down
DC-265-136	Interior, room 501, looking southeast
DC-265-137	Interior, room 501, looking southwest
DC-265-138	Interior, room 501, looking west
DC-265-139	Interior, room 5S1, looking east
DC-265-140	Interior, room 5S1, looking east at railing to right of elevator

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-141	Interior, room 5S1, close-up of same view seen in photograph HABS DC-265-140
DC-265-142	Interior, room 5S1, looking north
DC-265-143	Interior, room 5S1, looking south
DC-265-144	Interior, service stairs, looking southwest at the now covered opening that originally lighted the stairwell in photographs HABS No. DC-265-139 to DC-265-141
DC-265-145	Interior, room 502, looking north
DC-265-146	Interior, room 502, looking south
DC-265-147	Interior, room 502, looking southwest
DC-265-148	Interior, room 503, looking south
DC-265-149	Interior, room 503, looking north, vault door slightly open
DC-265-150	Interior, room 504, looking south
DC-265-151	Interior, room 504, ceiling medallion
DC-265-152	Interior, room 504, looking west at the fireplace and balcony
DC-265-153	Interior, balcony off room 504, looking northwest
DC-265-154	Interior, room 504, east wall
DC-265-155	Interior, room 504, east wall, south door
DC-265-156	Interior, room 504, north wall
DC-265-157	Interior, room 504, north wall, closer view
DC-265-158	Interior, room 504, north wall, close-up of door
DC-265-159	Interior, room 505, looking south
DC-265-160	Interior, room 505, east wall
DC-265-161	Interior, room 505, looking northwest
DC-265-162	Interior, room 505, looking northwest, closer view
DC-265-163	Interior, room 505, close-up of fireplace and triple double windows shown in HABS No. DC-265-161 and DC-265-162
DC-265-164	Interior, room 505, east wall
DC-265-165	Interior, room 506, south wall
DC-265-166	Interior, room 506, west wall
DC-265-167	Interior, room 506, north wall
DC-265-168	Interior, room 506, east wall
DC-265-169	Interior, room 507, looking east

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-170	Interior, room 507, looking west
DC-265-171	Interior, room 508, looking west
DC-265-172	Interior, room 508, looking east
DC-265-173	Interior, room 509, north wall
DC-265-174	Interior, room 509, looking west
DC-265-175	Interior, room 509, south wall
DC-265-176	Interior, room 509, looking east
DC-265-177	Interior, room 510, west wall and most of south wall
DC-265-178	Interior, room 510, looking north
DC-265-179	Interior, room 511, looking south
DC-265-180	Interior, room 511, looking north
DC-265-181	Interior, room 511D (closet), looking east
DC-265-182	Interior, room 511C (closet), looking east
DC-265-183	Interior, room 512, south wall
DC-265-184	Interior, room 512, west wall
DC-265-185	Interior, room 512, north wall
DC-265-186	Interior, room 512, east wall
DC-265-187	Interior, room 512, east wall, looking at closet safe (room 512A)
DC-265-188	Interior, room 512A, looking southwest at safe
DC-265-189	Interior, room 513, north wall
DC-265-190	Interior, room 513, south wall
DC-265-191	Interior, room 514, west wall
DC-265-192	Interior, room 514, north wall
DC-265-193	Interior, room 514, east wall
DC-265-194	Interior, room 514, south wall
DC-265-195	Interior, room 515, looking south
DC-265-196	Interior, room 516, east wall
DC-265-197	Interior, room 516, north wall
DC-265-198	Interior, room 516, west wall
DC-265-199	Interior, room 516, south wall
DC-265-200	Interior, room 517, north wall
DC-265-201	Interior, room 518, west wall

MCCORMICK APARTMENTS
HABS DC-265
INDEX TO PHOTOGRAPHS

DC-265-202	Interior, room 518, looking south
DC-265-203	Interior, room 518, east wall
DC-265-204	Interior, room 519, looking east, on right stairs to lower mezzanine, in distance middle stairs to upper mezzanine
DC-265-205	Interior, upper mezzanine, room M503 (old National Trust Number on door), looking west
DC-265-206	Interior, upper mezzanine, room M502 (old National Trust Number on door), looking south
DC-265-207	Interior, lower mezzanine, looking west
DC-265-208	Interior, lower mezzanine, room 5A (old National Trust Number on door), south wall
DC-265-209	Interior, room 524, looking east
DC-265-210	Interior, room 520, looking east
DC-265-211	Interior, room 521, looking southeast
DC-265-212	Interior, room 523, looking northeast
DC-265-213	Interior, room 525, looking southwest




CAMERA POSITION: Exterior and Ground Floor

10

13 12

1785 Massachusetts Avenue, N.W.
Washington, D.C.
Ground Floor Plan

9



14

18

17


(Position of openings and walls are approximate)

16

15


6

CAMERA POSITION: Roof



(Position of openings and walls are approximate)


CAMERA POSITION: First Floor



(Position of openings and walls are approximate)




CAMERA POSITION: Second Floor



(Position of openings and walls are approximate)




CAMERA POSITION: Third Floor



(Position of openings and walls are approximate)


CAMERA POSITION: Fourth Floor



(Position of openings and walls are approximate)




CAMERA POSITION: Fifth Floor



(Position of openings and walls are approximate)

HABS NO. DC-265
(Page 37)
16


CAMERA POSITION: First and Fifth Floor Mezzanines




(Position of openings and walls are approximate)

CAMERA POSITION: Second and Fourth Floor Mezzanines

M401



126



(Position of openings and walls are approximate)