

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC,
WASH,
530A-

U.S. General Services Administration, Central Heating Plant
C and D Streets, between 12th and 13th Streets, SW.
Washington
District of Columbia

HABS No. DC-383

Documentation: 17 exterior photos (1977)
3 interior photocopies (n.d.)
1 data page (1980)

John S. Drust, Photographer 1977

- DC-383-1 GENERAL VIEW, INCLUDING SOUTH AND EAST ELEVATIONS (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-2 GENERAL VIEW, CLOSE-UP, INCLUDING SOUTH AND EAST ELEVATIONS (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-3 GENERAL VIEW, INCLUDING NORTH AND WEST ELEVATIONS (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-4 GENERAL VIEW, CLOSE-UP, INCLUDING NORTH AND WEST ELEVATIONS (4 x 5 NEGATIVE)
- DC-383-5 SOUTH AND EAST ELEVATIONS (2-1/4 x 2-3/4 NEGATIVE)
- DC-383-6 EAST AND NORTH ELEVATIONS (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-7 EAST AND NORTH ELEVATIONS, CLOSE-UP (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-8 SOUTH ELEVATION (4 x 5 NEGATIVE)
- DC-383-9 NORTH AND WEST ELEVATIONS (4 x 5 NEGATIVE)
- DC-383-10 DETAIL, WEST ENTRANCE (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-11 DETAIL, DECORATIVE PANEL, BREAKERS (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-12 DETAIL, DECORATIVE PANEL, HEAT EXCHANGER (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-13 DETAIL, DECORATIVE PANEL, BLOWER (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)
- DC-383-14 DETAIL, DECORATIVE PANEL, GENERATOR (CROPPED PRINT FROM 2-1/4 x 2-3/4 NEGATIVE)

U.S. General Services Administration, Central Heating Plant
HABS No. DC-383
Index to Photographs (Page 2)

- DC-383-15 DETAIL, DECORATIVE PANEL, ABOVE TOP FLOOR, WEST ELEVATION (4 x 5 NEGATIVE)
- DC-383-16 DETAIL, CLOSE-UP OF DECORATIVE PANEL, TOP FLOOR (4 x 5 NEGATIVE)
- DC-383-17 DETAIL, ROOF STRUCTURE (4 x 5 NEGATIVE)
- DC-383-18 INTERIOR, CATWALK AND PIPES (G.S.A. PHOTOCOPY, N.D.) (4 x 5 NEGATIVE)
- DC-383-19 INTERIOR, "CHILLER NO. 2" (G.S.A. PHOTOCOPY, N.D.) (4 x 5 NEGATIVE)
- DC-383-20 INTERIOR, COAL CHUTES (G.S.A. PHOTOCOPY, N.D.) (4 x 5 NEGATIVE)