

INDEX TO PHOTOGRAPHS

HABS  
DC,  
WASH,  
543-

Winder Building  
NW corner 17th & F Sts., NW  
Washington  
District of Columbia

DC-392

Documentation: 13 sheets (1976, including plans, elevations, sections, details)  
6 exterior photos (1975)  
10 interior photos (1975)  
1 data page (1982)  
1 set of field records (including 2 historical reports:  
"The Winder Building and Its Environment" by OAHP, NPS, 1974,  
55 pgs.; and "Winder's Building: Historic Architectural  
Research" by Richard Bergmann Architects, 1976, 84 pages)

Photographer unknown July 1975

- DC-392-1 EAST FRONT
- DC-392-2 SOUTH SIDE AND EAST FRONT
- DC-392-3 SOUTH SIDE
- DC-392-4 WEST SIDE
- DC-392-5 WEST SIDE FROM NORTHWEST
- DC-392-6 NORTH SIDE
- DC-392-7 INTERIOR, 17TH ST. ENTRANCE
- DC-392-8 INTERIOR, FIRST-FLOOR CORRIDOR, 17TH ST. SIDE
- DC-392-9 INTERIOR, FIRST-FLOOR CORRIDOR, F ST. SIDE
- DC-392-10 INTERIOR, F ST. ENTRANCE
- DC-392-11 INTERIOR, SECOND-FLOOR CORRIDOR, F ST. SIDE
- DC-392-12 INTERIOR, STAIRWAY
- DC-392-13 INTERIOR DETAIL, CAST-IRON STAIRWAY
- DC-392-14 INTERIOR, SECOND-FLOOR MAIN OFFICE
- DC-392-15 INTERIOR, TYPICAL OFFICE
- DC-392-16 INTERIOR, BASEMENT