

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ATKINS HALL (Building 31)
St. Elizabeths West Campus
Redwood Drive SE
Washington, D.C.

HABS No. DC-349-T

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Leslie Schwartz, photographer, August 2010

- DC-349-T-1. North (side) facade, view from northeast
- DC-349-T-2. West (front) facade, view from northwest
- DC-349-T-3. South (side) facade showing porch, view from southeast
- DC-349-T-4. South porch to Relief (Building 32), view from southwest
- DC-349-T-5. South and east (rear) facade with porch, view from southeast
- DC-349-T-6. West facade center door and stair detail, view from southwest
- DC-349-T-7. West facade northwest stair and window detail, view from west
- DC-349-T-8. Basement showing stair, view from east
- DC-349-T-9. Basement showing tunnel system, west wall, view from east
- DC-349-T-10. First floor former Sitting Room, southeast corner, view from northeast corner of room
- DC-349-T-11. First floor former Reception Room, southwest corner, view from northeast
- DC-349-T-12. First floor former Reception Room, east wall, view from west