

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

CENTER BUILDING (Buildings 1 and 2)
St. Elizabeths West Campus
539–559 Cedar Drive SE
Washington, D.C.

HABS No. DC-349-W

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Leslie Schwartz, photographer, March 2011.

- DC-349-W-1. Partial north (front) facade, view from north
- DC-349-W-2. North facade, view from north
- DC-349-W-3. Partial north facade, view from northwest
- DC-349-W-4. Porte cochère on the north facade, view from northwest
- DC-349-W-5. Partial north facade, view from north
- DC-349-W-6. Partial north and east (side) facades, view from northeast
- DC-349-W-7. Partial south (rear) facade, view from south
- DC-349-W-8. Partial south facade, view from southeast
- DC-349-W-9. South entry door, view from south
- DC-349-W-10. Partial south and east facades, view from southeast
- DC-349-W-11. Partial south, east, and west (side) facades, view from south
- DC-349-W-12. Partial south facade, view from south, Bakery (Building 46) in foreground
- DC-349-W-13. Partial south facade, view from southwest
- DC-349-W-14. Partial west facade, view from west
- DC-349-W-15. Partial south facade, view from southeast
- DC-349-W-16. West lavatory addition, view from southwest
- DC-349-W-17. Basement level, view from south

ST. ELIZABETHS HOSPITAL
CENTER BUILDING (BUILDINGS 1 AND 2)
HABS No. DC-349-W
INDEX TO PHOTOGRAPHS (Page 2)

- DC-349-W-18. Basement level, view from northeast
- DC-349-W-19. Entrance vestibule, view from north
- DC-349-W-20. First floor main corridor, view from south
- DC-349-W-21. First floor superintendent's office, view from south
- DC-349-W-22. First floor matron's room, view from southwest
- DC-349-W-23. First floor corridor, view from west
- DC-349-W-24. First floor lavatory, view from northwest
- DC-349-W-25. First floor bedroom doorway, view from north
- DC-349-W-26. Second floor sitting room, view from north
- DC-349-W-27. Second floor corridor, view from south
- DC-349-W-28. Second floor sitting room, view from southeast
- DC-349-W-29. Second floor sitting room ceiling, view from west
- DC-349-W-30. Second floor east sitting room fireplace, view from northeast
- DC-349-W-31. Second floor south office, view from east
- DC-349-W-32. Second floor pantry, view from south
- DC-349-W-33. Second floor lavatory doorway, view from north
- DC-349-W-34. Third floor staircase, view from northwest
- DC-349-W-35. Second floor alcove, view from southeast
- DC-349-W-36. Third floor corridor, view from southwest
- DC-349-W-37. Third floor office, view from southeast
- DC-349-W-38. Fourth floor staircase, view from southeast
- DC-349-W-39. Third floor gymnasium, view from southwest