

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

WASHINGTON CANOE CLUB
3700 Water Street Northwest
Washington
District of Columbia

HABS DC-876

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Renee Bieretz, photographer, September 2012

- | | |
|-----------|---|
| DC-876-1 | Perspective view of south (front) façade looking northwest from pier. |
| DC-876-2 | Elevation view of south (front) façade looking north from pier. |
| DC-876-3 | Perspective view of south (front) façade looking northeast. |
| DC-876-4 | View of west tower (located at southwest corner), looking northeast. |
| DC-876-5 | View of east tower located between the original 1904 structure and the ca. 1930 boat shed addition looking northeast. |
| DC-876-6 | Oblique view of south (front) façade and eastern addition looking west. |
| DC-876-7 | Perspective view of the east (side) and north (rear) façades looking southwest. |
| DC-876-8 | Perspective view of west (side) and north (rear) façades looking southeast. |
| DC-876-9 | Detail view of sign on south (front) façade. |
| DC-876-10 | View of ground floor canoe storage area looking northwest. |
| DC-876-11 | View looking southeast in first floor "Grill Room" with mural. |
| DC-876-12 | Detail view of mural on west wall of "Grill Room." |

WASHINGTON CANOE CLUB
HABS DC-876
INDEX TO PHOTOGRAPHS

- DC-876-13 Detail view of mural looking northwest at corner of "Grill Room."
- DC-876-14 Detail view of mural on north wall of "Grill Room."
- DC-876-15 Detail view of "Grill Room" mural and doorway into kitchen looking north.
- DC-876-16 Detail view of mural looking northeast at corner.
- DC-876-17 Detail view of mural on east wall.
- DC-876-18 Detail view of mural on east wall.
- DC-876-19 Detail of mural on south wall with exterior rendering of Washington Canoe Club.
- DC-876-20 View of west and south walls looking west in ballroom. Note band stand to left of image.
- DC-876-21 Elevation view of ballroom showing north wall fire place and cabinets.
- DC-876-22 Elevation view of ballroom showing north wall fire place and cabinets with scale.
- DC-876-23 View of east wall looking south at benches in ballroom.
- DC-876-24 View looking east at second floor hall from ballroom.
- DC-876-25 View of south wall of "Board Room" on second floor looking southwest.
- DC-876-26 View looking northwest in shop addition (former roof deck) showing the original south and east exterior walls of main building and south façade of women's locker room.
- DC-876-27 View looking southeast of typical locker in women's locker room.
- DC-876-28 View looking south in men's locker room showing first level of lockers and loft area above.
- DC-876-29 View looking north in men's locker room from loft level.

INDEX TO COLOR TRANSPARENCIES

WASHINGTON CANOE CLUB
HABS DC-876
INDEX TO PHOTOGRAPHS

Renee Bieretz, photographer, September 2012

DC-876-30 (CT)	Detail view of sign on north façade.
DC-876-31 (CT)	Detail view of mural on west wall of "Grill Room."
DC-876-32 (CT)	Detail view of mural looking northwest at corner of "Grill Room."
DC-876-33 (CT)	Detail view of mural on north wall of "Grill Room."
DC-876-34 (CT)	Detail view of "Grill Room" mural and doorway into kitchen looking north.
DC-876-35 (CT)	Detail view of mural looking northeast at corner.
DC-876-36 (CT)	Detail view of mural on east wall.
DC-876-37 (CT)	Detail view of mural on east wall looking northeast.
DC-876-38 (CT)	Detail of mural on south wall looking southwest.