

HABS
DE L,
1-DOV.V,
3-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Kingston-Upon-Hull
(Town Point)
Kitts Hummock Rd.
Dover vicinity
Kent County
Delaware

HABS No. DE-175

Documentation: 6 sheets (1975, including site plan, plans, elevations)
10 exterior photos (1982)
2 interior photos (1982)
12 data pages (1975)
1 set of field records (1 notebook, 24 photos)

Jack E. Boucher, Photographer July, 1982

- DE-175-1 SOUTHWEST FRONT
- DE-175-2 SOUTHWEST FRONT FROM SOUTH
- DE-175-3 SOUTHEAST AND NORTHEAST SIDES
- DE-175-4 NORTHEAST SIDE
- DE-175-5 NORTHEAST SIDE, FROM NORTH
- DE-175-6 NORTHEAST SIDE, OBLIQUE VIEW
- DE-175-7 NORTHEAST SIDE
- DE-175-8 WEST CORNER
- DE-175-9 SOUTHWEST SIDE FROM WEST
- DE-175-10 DETAIL OF WINDOWS AND WATER TABLE, SOUTHWEST SIDE
- DE-175-11 INTERIOR, DINING ROOM, SOUTHEAST WALL
- DE-175-12 INTERIOR, SECOND FLOOR, STAIRWAY AND HALL

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
DEL
1-DOV.V,
3-

ADDENDUM TO
KINGSTON-UPON-HULL
Kitts Hummock Road
Dover Vicinity
Kent County
Delaware

HABS No. DE-175
(Page 2)

Photographer: David Ames

June 1992

Twelve photographs were previously transmitted to the Library of Congress.

- | | |
|-----------|--|
| DE-175-13 | PERSPECTIVE OF NORTHWEST AND NORTHEAST SIDES LOOKING SOUTH |
| DE-175-14 | DETAIL OF STEPPED WATER TABLE ON NORTHWEST WALL LOOKING SOUTHEAST |
| DE-175-15 | DETAIL OF SEGMENTAL ARCH, STEPPED WATER TABLE, AND CELLAR WINDOW ON NORTHWEST WALL LOOKING NORTHEAST |
| DE-175-16 | FIRST FLOOR: NORTHEAST AND SOUTHWEST WALLS OF SOUTHEAST ROOM LOOKING SOUTH |
| DE-175-17 | FIRST FLOOR: SOUTHWEST WALL OF CENTER ROOM LOOKING SOUTHWEST |
| DE-175-18 | FIRST FLOOR: NORTHWEST WALL OF CENTER ROOM LOOKING NORTHWEST |
| DE-175-19 | SECOND FLOOR: VIEW IN HALL LOOKING TOWARD NORTHWEST WALL |
| DE-175-20 | CELLAR: DETAIL OF PAIRED RELIEVING ARCH AND REMAINS OF HERRINGBONE BRICK PATTERN FROM EARLIER COOKING FIREPLACE AT BACK, SOUTHEAST WALL LOOKING SOUTHEAST |