

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
3-BRIVI,
1-

Dr. John R. Sudler House
North Main Street
Bridgeville
Sussex County
Delaware

DE-184

Documentation: 5 sheets (1975, including site plan, plans, elevations)
5 exterior photos (1982)
6 interior photos (1982)
8 data pages (1975)
1 set of field records (1 notebook, 4 photos)

Jack E. Boucher, Photographer July, 1982

- DE-184-1 NORTH END AND WEST FRONT
- DE-184-2 WEST FRONT FROM NORTH
- DE-184-3 WEST FRONT
- DE-184-4 WEST FRONT
- DE-184-5 WEST FRONT AND SOUTH END
- DE-184-6 STAIR HALL, LOOKING EAST
- DE-184-7 STAIR HALL, DETAIL OF STAIRWAY TRIM
- DE-184-8 STAIR HALL, DETAIL OF HINGE ON DINING ROOM DOOR
- DE-184-9 PARLOR, DETAIL OF PLINTH BLOCK ON DOORWAY
- DE-184-10 NORTH BEDROOM, LOOKING NORTHWEST
- DE-184-11 SOUTH BEDROOM, DETAIL OF CORNICE MOLDING

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
DR. JOHN R. SUDLER HOUSE
North Main Sreet
Bridgeville
Sussex County
Delaware

HABS No. DE-184

DE-184-1 through DE-184-11 were transmitted to the Library of Congress in 1983.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, July 1982

DE-184-12 (CT) WEST FRONT FROM THE NORTH