

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
 DEL,
 2-WILM.V,
 3-

Rockwood (Shipley-Bringhurst-Hargraves Mansion)
 610 Shiplev Road
 Wilmington Vicinity
 New Castle County
 Delaware

HABS No. DE-186

Photographer: David Ames

July 1982

- DE-186-1 VIEW SOUTH SHOWING NORTHEAST AND NORTHWEST (FRONT) ELEVATIONS
- DE-186-2 VIEW SOUTH, NORTHWEST (FRONT) ELEVATION OF 1851 PORTION OF HOUSE
- DE-186-3 VIEW SOUTH, DETAIL OF NORTHWEST (FRONT) ELEVATION
- DE-186-4 VIEW SOUTH, DETAIL OF GABLE OVER NORTHWEST (FRONT) ENTRY
- DE-186-5 VIEW SOUTHEAST SHOWING NORTHWEST ELEVATION OF POST 1851 ADDITIONS
- DE-186-6 VIEW NORTH SHOWING SOUTHWEST AND SOUTHEAST ELEVATIONS OF POST 1851 ADDITIONS
- DE-186-7 ENVIRONMENTAL VIEW NORTHWEST SHOWING SOUTHEAST ELEVATION
- DE-186-8 VIEW NORTHWEST SHOWING SOUTHEAST ELEVATION OF 1851 PORTION OF HOUSE
- DE-186-9 VIEW WEST SHOWING SOUTHEAST ELEVATION
- DE-186-10 VIEW SOUTHWEST SHOWING NORTHEAST ELEVATION AND CONSERVATORY
- DE-186-11 FIRST FLOOR, ENTRY HALL AND STAIRCASE LOOKING NORTH
- DE-186-12 FIRST FLOOR, ENTRY HALL LOOKING SOUTHEAST
- DE-186-13 SECOND FLOOR, VIEW OF ENTRY HALL FROM ABOVE
- DE-186-14 CONSERVATORY INTERIOR LOOKING SOUTHWEST
- DE-186-15 CONSERVATORY INTERIOR LOOKING NORTHEAST
- DE-186-16 CONSERVATORY, DETAIL OF CAST IRON COLUMNS LOOKING NORTHEAST
- DE-186-17 CONSERVATORY, DETAIL OF BAY AT NORTHEAST END LOOKING NORTHEAST
- DE-186-18 CONSERVATORY, ROOF AND NORTHWEST WALL LOOKING NORTH
- DE-186-19 CONSERVATORY, DETAIL OF BRACKETS ON NORTHWEST WALL LOOKING NORTH
- DE-186-20 CONSERVATORY, DETAIL OF BRACKETS, PENDANT AND TRUSS
- DE-186-21 VIEW NORTHWEST SHOWING SOUTHEAST ELEVATION OF BARN