

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
GA
143-LAGR,
29-

HILLSIDE COTTON MILL
(Milliken & Co. Textiles, Hillside Plant)
1300 Brownwood Avenue
LaGrange
Troup County
Georgia

HAER No. GA-130

Jet Lowe, HAER Photographer, April 2000

- GA-130-1 EXTERIOR VIEW OF HILLSIDE PLANT FROM INTERSECTION OF LINCOLN STREET AND 2ND AVENUE. HILLSIDE PLANT WAS BUILT AS CALLAWAY MILLS HILLSIDE COTTON MILL (PARK A. DALLIS, 1914-15). THIS TWO-STORY SECTION WAS BUILT AS A WEAVE SHED.
- GA-130-2 EXTERIOR VIEW OF HILLSIDE PLANT ENTRANCE. NOTE CONTRAST BETWEEN THIS MODERN ADDITION AND THE OLDER SECTION OF THE MILL VISIBLE IN HAER No. GA-130-1.
- GA-130-3 EXTERIOR VIEW OF CURRENT YARN PLANT. THE BOILER PLANT IS ON THE LEFT. THIS THREE-STORY SECTION WAS BUILT AS THE MAIN MILL HOUSING SPINNING RELATED PROCESSES. THIS END OF THE STRUCTURE WAS THE PICKER ROOM. NOTE THE FIRE WALL VISIBLE FOUR BAYS IN ON THE LEFT.
- GA-130-4 INTERIOR VIEW OF THIRD FLOOR OF YARN PLANT, CURRENTLY HOUSING CARDING AND TWISTING PROCESSES.
- GA-130-5 INTERIOR VIEW OF STAIRWELL NEAR WARPING AREA.
- GA-130-6 EXTERIOR VIEW OF DEVELOPMENT BUILDING. THIS STRUCTURE WAS BUILT AS A CLOTH WAREHOUSE AND IS LOCATED AT THE CENTER OF AN U-SHAPED GROUPING OF WAREHOUSES IN THE HILLSIDE MILL COMPLEX.
- GA-130-7 INTERIOR VIEW OF FIRST FLOOR IN FORMER CLOTH WAREHOUSE.
- GA-130-8 INTERIOR VIEW OF THIRD FLOOR IN FORMER CLOTH WAREHOUSE.