

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

U.S. Coast Guard Cutter MALLOW
Honolulu Vicinity
Honolulu County
Hawaii

HAER No. HI-61

The image is a photographic copy of an historic photograph located in the U.S. Coast Guard Historian's Office in Washington, D.C. The name of the photographer and the date are unknown.

HI-61-1 BUOY TENDING OPERATIONS ABOARD MALLOW. THIS VIEW SHOWS THE POWER VANGS (PULLEY SYSTEMS) THAT CONTROL THE CARGO BOOM AND THEIR ATTACHMENT POINTS ON THE BRIDGE WINGS. THIS CARGO HANDLING SYSTEM WAS USED ON "B" AND "C" CLASS TENDERS. THE "A" CLASS VESSELS SUPPORTED THEIR CARGO BOOM WITH AN A-FRAME.