

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Peak House
322 South Second
Manhattan
Riley County
Kansas

HABS No. KS-69

Documentation: 7 exterior photos (1994)
 8 interior photos (1994)
 14 data page (1994)

Earl Kintner, Photographer, October 1994

- | | |
|----------|--|
| KS-69-1 | SOUTH AND EAST SIDES OF HOUSE - AT OPEN INTERSECTION |
| KS-69-2 | FRONT OF HOUSE - SOUTH SIDE |
| KS-69-3 | EAST SIDE OF HOUSE |
| KS-69-4 | NORTH SIDE OF HOUSE |
| KS-69-5 | WEST SIDE OF HOUSE |
| KS-69-6 | DETAIL FRONT DOOR - SOUTH SIDE |
| KS-69-7 | DETAIL WINDOW - SOUTH SIDE OF HOUSE |
| KS-69-8 | EAST SIDE GABLE TREATMENT ON TWO-STORY SECTION OF HOUSE |
| KS-69-9 | INTERIOR DOOR IN SOUTHEAST ROOM - OPENS TO FOYER |
| KS-69-10 | INTERIOR TRIM DETAIL IN TWO-STORY SECTION OF HOUSE |
| KS-69-11 | INTERIOR TRIM DETAILING OF WINDOWS AND DOORWAYS OF TWO-STORY SECTION OF HOUSE |
| KS-69-12 | STAIRWAY LOOKING SOUTH TO SECOND STORY |
| KS-69-13 | SECOND STORY STAIRWAY RAILING AND BANISTER - REPLACEMENT NEWEL |
| KS-69-14 | INTERIOR - MOLDING SURROUNDING HOPPER WINDOWS ON SECOND STORY |
| KS-69-15 | INTERIOR - SECOND STORY WEST WALL SHOWING OAK WALL PROTECTORS ON CORNERS OF ENCLOSED CHIMNEY |