

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Curve Station
Intersection of Highway K-383 and Bryant Road
Vicinity of Almena
Norton County
Kansas

HABS No. KS-70

Documentation: 10 exterior photos (1994)
 7 interior photos (1994)
 18 data pages (1994)

Earl Kintner, Photographer, October 1994

KS-70-1	SOUTHEAST AND NORTHEAST SIDE OF BUILDING
KS-70-2	SOUTHEAST AND SOUTHWEST PERSPECTIVE
KS-70-3	FRONT, SOUTHEAST SIDE
KS-70-4	NORTHEAST SIDE OF BUILDING
KS-70-5	BACK, NORTHWEST SIDE
KS-70-6	NORTHEAST AND NORTHWEST SIDES OF BUILDING
KS-70-7	SOUTHWEST SIDE OF BUILDING
KS-70-8	FRONT GABLE AND DOORWAY
KS-70-9	FRONT, LEFT WINDOW
KS-70-10	EAVE DETAIL, NORTHWEST SIDE
KS-70-11	INTERIOR, LOOKING NORTHEAST (RESTROOM AREA)
KS-70-12	INTERIOR, LOOKING EAST
KS-70-13	INTERIOR, SOUTHWEST CORNER
KS-70-14	INTERIOR, LOOKING SOUTHEAST
KS-70-15	INTERIOR, EAST PART SOUTHEAST WALL
KS-70-16	INTERIOR, SOUTHWEST WALL
KS-70-17	INTERIOR, WEST HALF NORTHWEST WALL