

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

National Home for Disabled Volunteer Soldiers
Western Branch,
Single Quarters
(Building 52)
Franklin Avenue
Leavenworth
Leavenworth County
Kansas

HABS No. KS-55-B

Documentation: 5 Exterior Photographs (1993)
2 Interior Photographs (1993)

Key to Photographs: See Page 7 of written narrative

Photographer: Robert Brewster, Warren Jagger Photography, Inc., Providence, Rhode Island, June 1993

- KS-55-B-1 VIEW TO THE SOUTHWEST OF THE FRONT (EAST) WITH PORCH
- KS-55-B-2 VIEW TO THE SOUTHEAST OF THE SIDE (NORTH) AND REAR (WEST)
- KS-55-B-3 VIEW TO THE EAST OF THE REAR (WEST)
- KS-55-B-4 VIEW TO THE NORTHWEST OF THE SIDE (SOUTH)
- KS-55-B-5 DETAIL VIEW TO THE SOUTH OF A FRONT ENTRY DOOR
- KS-55-B-6 INTERIOR VIEW TO THE NORTHWEST OF THE FIRST FLOOR ENTRY HALL AND STAIRCASE
- KS-55-B-7 INTERIOR VIEW TO THE SOUTHEAST OF A SECOND FLOOR BEDROOM