

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

GEORGE SPANGERBERGER FARMSTEAD, RESIDENCE
2012 W. Illinois Ave.
South Hutchinson Vicinity
Reno County
Kansas

HABS No. KS-77-A

Documentation: 4 exterior photos
 24 interior photos
 7 data pages

Photographer: Larry Colcher, July and November 1997

- KS-77-A-1 FRONT (SOUTH) SIDE OF RESIDENCE
- KS-77-A-2 FRONT AND EAST SIDES OF RESIDENCE
- KS-77-A-3 REAR (NORTH) AND WEST SIDES OF RESIDENCE
- KS-77-A-4 REAR AND EAST SIDES OF RESIDENCE
- KS-77-A-5 INTERIOR VIEW OF RESIDENCE, MAIN PARLOR, LOOKING SOUTHWEST
- KS-77-A-6 INTERIOR VIEW OF RESIDENCE, MAIN PARLOR, LOOKING WEST
- KS-77-A-7 INTERIOR VIEW OF RESIDENCE, MAIN PARLOR, DETAIL OF ADDED CLOSET, LOOKING WEST
- KS-77-A-8 INTERIOR VIEW OF RESIDENCE, MAIN PARLOR, LOOKING EAST
- KS-77-A-9 INTERIOR VIEW OF RESIDENCE, SOUTHWEST BEDROOM, LOOKING SOUTHWEST
- KS-77-A-10 INTERIOR VIEW OF RESIDENCE, SOUTHWEST BEDROOM, DETAIL OF BLOCKED OFF DOOR TO MAIN PARLOR, LOOKING EAST
- KS-77-A-11 INTERIOR VIEW OF RESIDENCE, SOUTHWEST BEDROOM, LOOKING NORTHEAST
- KS-77-A-12 INTERIOR VIEW OF RESIDENCE, CLOSET NORTH OF SOUTHWEST BEDROOM, LOOKING NORTHEAST
- KS-77-A-13 INTERIOR VIEW OF RESIDENCE, SECONDARY PARLOR OR LIVING ROOM, LOOKING NORTHWEST
- KS-77-A-14 INTERIOR VIEW OF RESIDENCE, SECONDARY PARLOR OR LIVING ROOM, LOOKING NORTHEAST
- KS-77-A-15 INTERIOR VIEW OF RESIDENCE, SECONDARY PARLOR OR LIVING ROOM, LOOKING SOUTH
- KS-77-A-16 INTERIOR VIEW OF RESIDENCE, BATH, LOOKING NORTHWEST
- KS-77-A-17 INTERIOR VIEW OF RESIDENCE, DINING OR GENERAL ENTRY ROOM, LOOKING SOUTH

KS-77-A-18 INTERIOR VIEW OF RESIDENCE, DINING OR GENERAL ENTRY ROOM, LOOKING EAST

KS-77-A-19 INTERIOR VIEW OF RESIDENCE, DINING OR GENERAL ENTRY ROOM, LOOKING NORTH

KS-77-A-20 INTERIOR VIEW OF RESIDENCE, DINING OR GENERAL ENTRY ROOM, LOOKING WEST

KS-77-A-21 INTERIOR VIEW OF RESIDENCE, KITCHEN, LOOKING SOUTHWEST

KS-77-A-22 INTERIOR VIEW OF RESIDENCE, UTILITY ROOM, LOOKING NORTH

KS-77-A-23 INTERIOR VIEW OF RESIDENCE, WEST PORCH, LOOKING WEST


KS-77-A-24 INTERIOR VIEW OF RESIDENCE, WEST PORCH, LOOKING SOUTH

KS-77-A-25 INTERIOR VIEW OF RESIDENCE, EAST PORCH, LOOKING SOUTH WITH TRAP DOOR TO CELLAR OPEN


KS-77-A-26 INTERIOR VIEW OF RESIDENCE, EAST PORCH, LOOKING SOUTH DOWN CELLAR STAIRS

KS-77-A-27 INTERIOR VIEW OF RESIDENCE, CELLAR, LOOKING EAST

KS-77-A-28 INTERIOR VIEW OF RESIDENCE, CELLAR, LOOKING WEST



KEY TO EXTERIOR PHOTOGRAPHS OF THE
GEORGE SPANGERBERGER FARMSTEAD, RESIDENCE.




W= Windows

D= Doors



- 1 Main Parlor
- 2 Southwest Bedroom
- 3 Secondary Parlor or Living Room
- 4 Bath
- 5 Dining or General Entry Room
- 6 Kitchen
- Cl Closet

KEY TO INTERIOR PHOTOGRAPHS OF THE
 GEORGE SPANGERBERGER FARMSTEAD, RESIDENCE, FIRST FLOOR.



KEY TO INTERIOR PHOTOGRAPHS OF THE
GEORGE SPANGERBERGER FARMSTEAD, RESIDENCE, CELLAR.