

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Claiborne Robinson House HABS No. KY-221
113 North Mulberry Street *North Mulberry-Oregon Street Neighborhood*
Georgetown
Scott County
Kentucky

Charles Perkins, Photographer July 1991

- KY-221-1 VIEW OF FRONT OF HOUSE; LOOKING NORTHWEST.
- KY-221-2 VIEW OF FRONT OF HOUSE, LOOKING SOUTHWEST.
- KY-221-3 VIEW OF FRONT OF HOUSE, LOOKING NORTHWEST.
- KY-221-4 VIEW OF REAR AND SOUTH WALL OF HOUSE, LOOKING NORTHEAST.
- KY-221-5 VIEW OF EAST (FRONT) WALL FROM INTERIOR OF FRONT ROOM, SHOWING FRONT DOOR AND WINDOW; LOOKING EAST.
- KY-221-6 VIEW OF EAST (FRONT) WALL FROM INTERIOR OF FRONT WALL, SHOWING FRONT AND WINDOW; LOOKING EAST.
- KY-221-7 VIEW OF EAST WALL OF THE MIDDLE ROOM, SHOWING CONNECTING DOOR TO FRONT ROOM AND MANTLE ASSOCIATED WITH CORNER CHIMNEY FLUE. LOOKING EAST.
- KY-221-8 VIEW OF EAST WALL OF THE MIDDLE ROOM, SHOWING CONNECTING DOOR TO FRONT ROOM AND MANTLE ASSOCIATED WITH CORNER CHIMNEY FLUE. LOOKING EAST.
- KY-221-9 VIEW OF SOUTHWEST CORNER OF FRONT ROOM, SHOWING IRON MANTLE AND CONNECTING DOOR TO MIDDLE ROOM. LOOKING SOUTHWEST.
- KY-221-10 VIEW OF EAST WALL OF REAR ROOM (LABELLED KITCHEN IN FLOOR PLAN) SHOWING CONNECTING DOOR TO MIDDLE ROOM AND WAINSCOT. LOOKING EAST.
- KY-221-11 VIEW OF EAST WALL OF REAR ROOM (LABELLED KITCHEN IN FLOOR PLAN) SHOWING CONNECTING DOOR TO MIDDLE ROOM AND WAINSCOT. LOOKING EAST.
- KY-221-12 VIEW OF WEST WALL OF REAR ROOM (LABELLED KITCHEN ON FLOOR PLAN) SHOWING REAR DOOR TO EXTERIOR, WINDOW AND WAINSCOT. LOOKING WEST.