

HABS
MD
17-MARBU.V,
3-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum To:
COMPTON BASSETT
16508 Marlboro Pike
Upper Marlboro
Prince George's County
Maryland

Jack Boucher, photographer, March 1989

Four photographs were previously transmitted to the Library of Congress, taken in 1936 and 1937.

- MD-134-5 GENERAL VIEW, SOUTHEAST FRONT, FROM EAST
- MD-134-6 VIEW, SOUTHEAST (FRONT) ELEVATION
- MD-134-7 SOUTHEAST ELEVATION, WITH SCALE
- MD-134-8 GENERAL VIEW, SOUTHEAST (FRONT) AND SOUTHWEST (SIDE), FROM SOUTH
- MD-134-9 MAIN HOUSE, NORTHWEST (REAR) FACADE ELEVATION, WITHOUT SCALE
- MD-134-10 VIEW, NORTHEAST WING FROM SOUTHEAST (WITH FLASH FILL)
- MD-134-11 INTERIOR VIEW, GENERAL VIEW, HALL AND STAIRS WITH PARTITION FROM SOUTHEAST
- MD-134-12 DETAIL VIEW, NEWELL, FROM NORTHEAST
- MD-134-13 VIEW, FROM WEST TO SUTHEAST IN CENTER HALL, TO FRONT DOOR
- MD-134-14 DETAIL VIEW, OVERDOOR, TO NORTHEAST WALL OF CENTER HALL

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
COMPTON BASSETT
(Clement Hill V House)
16508 Old Marlboro Pike
Upper Marlboro
Prince George's County
Maryland

HABS MD-134

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Renee Bieretz, photographer, February 2013

- | | |
|-----------|--|
| MD-134-15 | General view of barns, dairy, and house from west. |
| MD-134-16 | General view of dairy, house, and meathouse from west. |
| MD-134-17 | View of barns, dairy, and house from west. |
| MD-134-18 | Perspective view of house from south. |
| MD-134-19 | Side elevation (south) of house showing earthquake damage. |
| MD-134-20 | View of meathouse, dairy, and side elevation of house from south. |
| MD-134-21 | Interior view of south parlor from east. Note doorway to former doctor's office on left. |
| MD-134-22 | Detail view of doorway in south parlor looking across center hall. |
| MD-134-23 | Interior view of east front room (dining room) from south. |
| MD-134-24 | Interior view of former doctor's office at southwest corner of first floor. Note doorway to south parlor on right. |
| MD-134-25 | Palladian window at second floor stair hall from southeast. |
| MD-134-26 | Palladian window at second floor front room from northwest. |
| MD-134-27 | View of south second floor chamber from east. |
| MD-134-28 | Interior window detail at southeast wall of second floor east chamber. |

COMPTON BASSETT
HABS MD-134
INDEX TO PHOTOGRAPHS

- MD-134-29 Fireplace detail in west (rear) second floor chamber.
- MD-134-30 Detail in attic of southeast dormer with signature "A. L.
Gosnell" inscribed in plaster.