

407-431 West Lexington Street (Lexington  
Market Addition)  
413 West Lexington Street (Commercial  
Building)  
Baltimore (Independent City)  
Maryland

HABS No. MD-916-D

HABS  
MD,  
4-BALT,  
197D-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY  
MID-ATLANTIC REGION NATIONAL PARK SERVICE  
DEPARTMENT OF THE INTERIOR  
PHILADELPHIA, PENNSYLVANIA 19106

HABS  
MD.  
4-BALT,  
157D-

ARCHITECTURAL DATA FORM

|   |  |   |  |
|---|--|---|--|
| STATE<br>Maryland   |  | COUNTY  | TOWN OR VICINITY<br>Baltimore (Independent City) |
| HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)<br>407-431 West Lexington Street   |  |   | HABS NO.<br>MD-916-D                             |
| SECONDARY OR COMMON NAMES OF STRUCTURE<br>Lexington Market Addition<br>413 West Lexington Street (Commercial Building)  |  |   |  |
| COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)<br>413 West Lexington Street (Block 618, lot 19)   |  |   |  |
| DATE OF CONSTRUCTION (INCLUDE SOURCE)<br>circa 1890s (map research, architectural details)  |  | ARCHITECT(S) (INCLUDE SOURCE)<br>Unknown, probably none |  |
| SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)<br>Minor part of row with historic association with Lexington Market. Originally retail use related to market.   |  |   |  |
| STYLE (IF APPROPRIATE)<br>Late nineteenth century Italianate commercial (altered)   |  |   |  |
| MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)<br>Brick, common bond 5:1, timber floor and roof framing  |  |   |  |
| SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)<br>Rectangular, 18' x 60' including rear additions, shed roof   |  |   |  |
| EXTERIOR FEATURES OF NOTE<br>Pressed tin cornice; rest of facade lost when facade remodeled   |  |   |  |
| INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)<br>Tin ceiling, first floor; good slate mantel, second floor front. Two rooms deep at each floor, with stair along east wall to second. Stair to third floor between rooms of second floor. Minor late nineteenth-century trim at upper floors. |  |   |  |
| MAJOR ALTERATIONS AND ADDITIONS WITH DATES<br>First floor facade altered circa 1950s (glazed brick/glass bay front with simple pressed tin cornice); rear addition circa 1950 (map research)  |  |   |  |
| PRESENT CONDITION AND USE<br>Fair to poor; vacant, last used as bar-lounge  |  |   |  |
| OTHER INFORMATION AS APPROPRIATE<br>Russell Wright, AIA, Consultant, Market Center Development  |  |   |  |
| SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)<br>1980 Survey of the Baltimore Central Business District  |  |   |  |
| COMPILER, AFFILIATION<br>Russell Wright, AIA, Consultant, Market Center Development Corporation, Baltimore  |  |   | DATE<br>August 1981                              |