

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

CHITTENDEN NURSERY EXTRACTORY

HABS No. MI-407

1070 Nursery Rd.
Wellston Vicinity
Manistee County
Michigan

Photographer: Jerry Lewis Photographers, Inc.
342 River Street
Manistee, Michigan 49660

- MI-407-1 View of Northwest Exterior
- MI-407-2 View of Southeast Exterior
- MI-407-3 View of Southwest Exterior
- MI-407-4 View of Northeast Exterior
- MI-407-5 Basement Level, Electrical Box, North Wall
- MI-407-6 Upper Level, Southeast Corner, Stove Pipe and Cement Floor
- MI-407-7 Basement Level, Northeast Corner Room, View of Ash Shoot
- MI-407-8 Upper Level, Southwest Corner, Stairwell
- MI-407-9 Basement, Southeast Corner Room, Steam Pipe and Valve
- MI-407-10 Basement, Northwest Corner of Southeast Room; Pipe and Wiring
- MI-407-11 Basement, View of Stairwell